G.M.1930

101 & 30

Sr. No. 1-17.

P. 18

Report on the Condition of the Great-
Trigonometrical Survey Stations in the
State for the year 1930.

App. F. IX-4

Previous References

1931. (G.M)

File No. 101-3a

Serial Nos. 1-17

Later References

G.1776-32 & 1-23.

General and Revenue Secretariat.

Serial Nos. 17

Part B for Jany 32.

SUBJECT.

Report on the Condition of great Trigonometrical Survey stations in the state for the year 1930.

G. 2861-9 & 7.10.31

Records the report on the Condition of G. T-S. stations

K.
1/2/32

General and Revenue Secretariat

G.M. 101- (2110 / 2113)

App. F. III—2]

~~RP File No.~~ 77 ~~of 193~~ 0.

Serial No.	
	From the Dy Com Bangalore No C b Pa A 69 / 29-30 dt 10.12.30 forwarding an estimate for Rs 3 for repairing the G. T. Station at Devarajapura 321 S.
2	From the D.C Kolar No A-9-C/257 / 30-31 dt 11.12.30 forwarding the estimate for repairs to the G-T. Station No 154 6 Kundasandra HS Rathgal Rly
	The reports of the conditions of G. T. S Stations of the above Rly & those of the remaining Rly are awaited. Submitted for perusal
	Ky 17.12.30
	19/12/30

4979

This has been called for separately

NOTE—Contn. Sheet.

WD 02553—G PB—50,000—8 7 30

2340 2

App. F. III—2]

General and Revenue Secretariat

~~P.P.~~ File No. 77 ~~of 193-0.~~

Serial No.	
3	From the Dy Comm Hazaras Letter No C Per 99 dd 5.1.31 Forwards a report on the conviction of the E.T. Sr Shahnis in the Hazara Dn for the Calendar year 1930 in the prescribed form Asst Supdt (Calling for report from the Shahnis Dy Comm) by (2) Issued 7.1.31 (GR) 8/1/31
4	To the Dy Comm Hazara (Except Haripur) No. 2358-9 dd 5.1.31 Calls for the report of the conviction of the E.T. Shahnis
5	From the D C Tank No 7 C 6438 dd 7.1.31 ~~Forwards~~ submits the statement of inspection of the E.T. Shahnis in his Dn. (3) Subd. Reports of the remaining Shahnis are awaited by 9/1/31 (GR) (4) Year Dec 10/1/31
6	From the D.C Kohat No C Per 109/30-31 dd 9.1.31 Submits the statement of inspection of E.T.S

Sw file 20/1/31

NOTE—Contn. Sheet

VD 02553—50,000—GPB—8-7 30

General and Revenue Secretariat

File No. 47 of 1930

Serial No.	
10	From the Dy Comm Mysore D No Cer 11.5/30 d 17.1.31 Forwards the annual Report on the Condition of the G T S Stations From the Dy Comm Bangalore D No C.6/2244/30-31 d 16.1.31 Forwards the report of the Condition of the G.T.S Stations in his District (The estimate in respect of Adhanbetta H.S 439 in the Mysore D has not been sent) Subdi or perused, attached. by 19.1.31 (PPR) dcd 20/1/31 From the Dy. Commissioner, Chitaldrug. No. A.3 per A 171/30-31 dated 29-1-1931. Forwards the annual report on the condition of the several Trigonometrical survey stations in the district for the Year 1930. From the Dy. Commissioner, Bangalore No. C.6.-2244 dated 2-2-31. Forwards further report modifying the previous report of this District. From the Deputy Commissioner, Shimoga No. A.3. Pers A.4/30-31. dt 24-2-1931. Forwards a statement showing the condition of Trigonometrical survey stations in the Sagar Taluk

NOTE—Contn. Sheet

WD 02553—50,000—GPB—8-7-30

From the D.C. Kadur.
No. A 7.1846-30/48 dt 26-2-31.
Forwards an estimate for Rs 4/- for repairs to Ballalarayanadurga in Mudigere Taluk.

File No. 425 of 1931
154

General and Revenue Secretariat

5 Draft calling for certain information from the Secretariat Dept.

28/3

[illegible]

[illegible] available

[illegible] 2L 7-4-1931.

Furnishes certain information required and promises to send the rest.

Until further reports may be awaited.

[illegible]

From the D.C. Trichur

No 1470, 30-21 dated 3-4-1931.

Forwards his letter dated 13-1-31 ~~instead~~ instead of the one dated 5-1-1931 which was called for

From the D.C. Shimoga

No A3 1474 30-21 dated 14-4-1931.

Submits the information called for above

6 539 6

1079
1104
1117

App. F. III—2]

General and Revenue Secretariat 9 17 File No. 167 of 1930

Serial No.	
	Subd The D.C. Tumkur has sent the letter dated 13-1-31 instead of the one dated 5-1-31 which was called for in this office letter dated 2-4-1931 draft calling for the letter dated 5-1-31 subd. The reports of the D.Cs of Kolar, Chitaldrug and Bangalore will also be awaited. Yes 20/4 Wd/ Dft 17/4 Wd Yes dft 20/4 allay the draft in the file issue? Dft 22/4 Yes dft to D.C. Tumkur Wd 22/4
6	From: The D.C. Kolar No. A3.C.2159 dt 16-4-1931 furnishes certain information. From - The D.C. Chitaldrug. No. LC 1757 dt 18-4-1931 furnishes certain info From - The D.C. Kolar. No. L. 157 3.C.2164 dt 22/4/31 From - The D.C. Bangalore No. C6-2269 dt 22-4-31 From - The D.C. Kadur No. A.7-1846 dt 24-4-31 From - The D.C. Chitaldrug. No. A.3.C.1949 dt 27-4-31 From - The D.C. Tumkur No. C.1470 dt 8-5-31

NOTE.—Contn. Sheet

WD 02553—50,000—GPB—8-7 30

General and Re...
Secretariat

...1938 .

Subd. with a draft to the Vc Chilād dang
reporting to furnish certain information

CC
10/6

To the Vc Chilādang.

By 15-6-38

Please to intimate the Secretary
and Bank [illegible]

From the Vc Chilādang.

[illegible]

Subd. with a draft to the Secretary.
CC
[illegible]

[illegible] Kindly Verify
in the records whether the Dists.
have been correctly entered in the
Ex. Rep. & be rewarded in the
Register. The file marks required
in a case.

RS
26/6.

The Statements are being verified with the Collectorate records

[illegible] to whether
the E.C. Jamedars can be asked
to submit an estimate for repairs

Serial No.

to the Savandurga Hill Station as he has enquired whether an estimate should be submitted by him for the purpose or the Survey of India party will repair the station. However, a draft is put up for orders.

22/7 If approved the draft letter to the Residency, with the statement will issue.

(Chief Sec.) 23/7

That certain repairs are necessary has been mentioned in the statement. The Report to the Residency need not been delayed for want of the mention of specific amt. of cost of repair in this single case.

OFFICE 23 JULY 1931

nec 24/7/31

Issue 24/7

12 To the Hon'ble Resident.
No. Pol. S-5 of 11-7-1931
Forwarding the annual report of the Local Govt. of the G.T.S. Stations in the State for 1930-31

Sus 11/9

11 SEPT

13 From the Secretary to the Resident
No. 6772
382-1931 dt 17-9-1931

Forwards copy of letter no. 602/8-1 (a) 47.7.2/0, dt 18-8-1931 from the Director Geodetic Branch, Survey of India, Dehra Dun regarding allotment for repairs to the G.T.S. stations during 1931-32.

22/9 Submd. with a draft. Please put up a clean draft as revised, together with a draft letter to D.C's for. 22.9.31
(words) the forms etc.

NOTE—Contd. Sheet.

WD 02553—GPB—50,000—8-7-30

File No. of 191 General and Revenue Secretariat

[illegible]

[illegible] apld: these drafts will issue.

(On receipt of the other forms demanded by the Residency, they will be forwarded to the [illegible]).

[illegible] 23.9.21

[illegible]

1/10/21

To [illegible]

[illegible]

[illegible]

Records [illegible] annual report on the Constitution [illegible]

[illegible]

[illegible]

[illegible]

[illegible]

GENERAL SECRETARY. 23 SEP. 21 No.

TYPING SECTION

SEAL

B

[illegible] annual [illegible] included in the annual Report [illegible] Stations in the Sind that the [illegible] to the Residency with [illegible] 5 P.M. 10/-to-12 [illegible] The Residency [illegible] letter

290
567

(10

General and Revenue Secretariat — File No. 1648 — of 193 0. — [App. F. III—2

Serial No.

X M — dated 17-9-1931 stated that no allotment for repairs during of G.T.S stations during 1931-32 could be made owing to financial stringency. This was intimated to all the D.Cs of Dept in G.O.

X W — No G-2861-9/G.M-101-30-14 dt 7-10-1931 was sended with a draft for approval. Dy 31/12 If appd: the draft will come. dd 2.1.32

GENERAL SECRETARY. 2 JAN. 1932 No 4679

(Genl: Seq)

Rg 2/1/32

Issued dd 2-1-32

TYPING SECTION GEN'L T. 4. JAN '32

16 To the D.C Chitaldrug.

No. R.5477 of 8-1-1932

Sirs I am directed to request that the estimate may be included in the next yearly annual report

17 From the D.C Bangalore

No.C6-3269/30-31 dt 8-1-1932.

Forwards an estimate for Rs 50/- being the cost of repairs to the G.T.S. station at Savandurga

Y — kind reference is invited to G.O.

X Q — No G 2861-9/G.M 101-30-14 dt 7-10-1931 observing that owing to financial stringency it is not possible to make any allotment for repairs needed to the G.T.S stations during 1931-32. If approved the D.C, Bangalore will be asked to include this in the next annual

NOTE—Contn. Sheet.

In all future communications please quote—
No. C6-Per.A.69/29-30.
Enc. estimate for Rs.3/-.

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the 10th December 1930

FROM

Moin-Ul-Vizarath
A.K. Syed Taj Peeran, Esq., B.A.,
Deputy Commissioner,
Bangalore District.

To

R. Ranga Rao, Esq., B.A., B.L.,
Offg. Chief *Secretary,*
to the Government of Mysore.
Bangalore.

SIR,

Subject:—Re. the estimate for the repairs of Trigonometrical survey station at Lingarajapura 321 S.

In submitting herewith an estimate for Rs.3/- being the probable cost of repairs required for the above, I have the honour to request that the same may kindly be got sanctioned at an early date.

The enclosures on the subject accompany.

I have the honour to be,
Sir,
Your most obedient servant,

Deputy Commissioner,
Bangalore District.

SS/-

B2-660/29-30.

Sealed submitted to the Deputy Commissioner's Bangalore DC cattle refilled his sale receipt dt/21-1-30.

The estimate for the repairs of Trigonometrical Survey Station at Singa Rajapura, Kasaba Hobli Bangalore city Taluq. is here with Sealed submitted for sanction as called for.

9/9.
Seal-Division office
Bangalore Seal-Dt
9/9/30

COMMISSIONER'S OFFICE
11 SEPT. 1930
No. 5094
DIST.

Memo HC 461 — 4.30

B 2-660/4-80

Forwarded to the Amildar

Bangalore City Tq for submission of the estimate in the repairs required to Station No. 321 respectfully

Memberam by Sub Div Officer Bangalore Sub Div



HC 461/4.30

Kannada text

14-4-80
BH 50.
4.30

Kannada text

T. Venkatarangaiah
Sub Inspector

Extract from the Report of the
Meteorological Stations in Bengal
Sub-Division during the Calendar Year
being from the Sub-Division

× × × × ×

21 Chandbali. Records received

× × × ×
×

Remarks

I am to forward to the Sub-Division Officer
Baripada the early Sub-Inspector's
Station Diaries for the year required to enable him
to write his notes.

(Sd) V. Bhadra
for Deputy Commissioner.
N.I.S.D
P. T. C.

Estimate showing the repairs to be done to the Trignometrical Survey Station near Linganja pura Kasaba Hobli Bangalore city Taluq

Item no	details -	amount
	Sundry repairs Lumpsum -	3 - -
		3 - -

Countersigned for Rupees three only (Rs 3-0-0)
for Deputy Commissioner
By Order
Rs Mcanly
13/12

Received Rupees
Revenue Inspector

PP

In all future correspondence please quote
No. A-9-C.1251/30-31
Encl. One bill

OFFICE OF THE DEPUTY COMMISSIONER,
KOLAR DISTRICT,

Dated, Kolar, the 11th December *1930*.

PP 77-30-2

CP 2110

FROM

V. RAMANATHAN, ESQ., B.A.,
Deputy Commissioner,
Kolar District.

To

N.Madhava Rao, Esq., B.A., B.L.,
Chief Secretary to the Government of Mysore,
Bangalore.

SIR,

Re - repairs to Great Trigonometrical Station No.1946 Kurudamale H.S.Mulbagal Taluk.

I have the honor to state that the Amildar, Mulbagal Taluk, inspected the above station on 21st November 1930 and found it in good condition except at the corners of the mound on the sides, which needed replastering & cementing. Necessary repairs have been carried out by the Amildar and the estimate for the same is herewith submitted.

The Sub-Division officer in his No.R.1.C.553/30-31 dated 2nd December 1930 also recommends sanction of the bill of Re.1/-.

I request that the bill may kindly be passed and made payable to the Amildar, Mulbagal Taluk, in the Taluk Treasury, Mulbagal.

I have the honor to be,
Sir,
Your most obedient servant,

Devaraj Asst. Commissioner
for Deputy Commissioner,
Kolar District.
Absent from Station

RJ
13/12/30

V. P. 7]

ಟ್ಟಣಿಕೆ ವರ್ಕ್ಸ್‌ಗಳ (ಜನೋಪಯುಕ್ತವಾದ ಕಾಮಗಾರಿಗಳ) ಅಂದಾಜು.

WD 0582—GPB—10,000 books of 50 pp. each—30-8-27

ಕಾಮಗಾರಿಯ ವಿವರ	ನಂಬರು ಅಳತೆ: ಉದ್ದ	ನಂಬರು ಅಳತೆ: ಅಗಲ ಅಥವಾ ದಪ್ಪ	ನಂಬರು ಅಳತೆ: ಎತ್ತರ ಅಥವಾ ಆಳ	ವಿವರಗಳು	ಕಾಮಗಾರಿಯ ಪ್ರತಿಯೊಂದು ವಿವರದ ಒಟ್ಟು ಪ್ರಮಾಣ	ದರ ರೂ.	ದರ ಆ.	ದರ ಪೈ.	ಖರ್ಚು ರೂ.	ಖರ್ಚು ಆ.	ಖರ್ಚು ಪೈ.	ಷರಾ
An estimate showing the probable Cost for the repair of the Trigonometrical station Pillar at Kurundimala, Uruggasandra Hobli												
1) Repair of a corner with cement and brick and cement pointing to the pillar four sides				Lumpsum work					1	-	-	
				Total Cost					1	-	-	

Estimate for Rs one only.

22/11/30

H. Venkatasubbaiah
Rev. Inspector

.....ರೂಪಾಯಿಗಳಿಗೆ ಮಂಜೂರ್ಮಾಡಲ್ಪಟ್ಟಿದೆ.

Abdulla Khan
Asst.

ತಾರೀಖು.....

ರುಜು ಮತ್ತು ಹುದ್ದೆಯ ಹೆಸರು.

ತಾರೀಖು 24/11/30

ಅಧ್ಯಕ್ಷನ ರುಜು.

C.Per.99Y.

OFFICE OF THE DEPUTY COMMISSIONER,
HASSAN DISTRICT.

Dated, Hassan, the 5th January 1931.

From

S. ABDUL WAJID, Esq, B.A.,

Deputy Commissioner, Hassan District.

To

P. MAHADEVAYYA, Esq., B.A., B.L.,
Secretary to the Government of His Highness
the Maharaja of Mysore, General Department
B a n g a l o r e.

Sir,

I have the honorto forward herewith a report on the condition of Trignometrical Survey stations in the Hassan District, for the calendar year 1930 in the prescribed form.

I have the honor to be,
S i r,
Your most obedient servant,
Abdul Wajid.
Deputy Commissioner,
Hassan District.

as.

(21)

Appendix F G—1

SUBJECT.....

.....

.....

Section PP

File No. 77-30

Serial No. 4

No. 2788-94.

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the *193*

To

The Dy. Commrs

(Except Hazara)

Date of issue 8-1-31

Sir,

I am directed

Signed by Asst D.G.S

request you to kindly

submit the annual

report of the Comr's his

of the Great Trigonometrical

Survey Sketches in your

Dt for the Calendar year

List of enclosures..... 1930 in the prescribed form.

I have the

Copied by..... dcg 8/1/31.

for Chief

Examined by..... 7/1/31

[over

WD 02559—GPB—25,000—25-6-30

GOVERNMENT OF HIS HIGHNESS THE MAHARAJA OF MYSORE

General and Revenue Secretariat

(22)

No. 2788-94
PP77-30-4

Dated, Bangalore, 8th January 1931.

From

N. MADHAVA RAO, Esq., B. A., B. L.,
Chief Secretary to the Government of His Highness the Maharaja of Mysore.

To

The Deputy Commissioner,

.....of.. Districts (except Hassan)

Sir,

I am directed to request you to kindly submit early the annual report of the condition of the Great Trignometrical Survey stations in your District for the calendar year 1930 in the prescribed form.

I have the honour to be,
Sir,
Your most obedient servant,

For Chief Secretary to Government

(23

No. Fc.64 38 – 30 – 31

Enc. One

OFFICE OF THE DEPUTY COMMISSIONER,
TUMKUR DISTRICT.

Dated Tumkur, the 7th January *1931*

FROM

G. B. HEBLIKAR, ESQ., B.A., LL.B.,
Deputy Commissioner,
Tumkur District, Tumkur.

CB 2362

PP 77-30-5

To

N. Madhava Rao, Esquire, B.A., B.L.,
Chief Secretary to the Government of
H. H. the Maharaja of Mysore, Bangalore.

9 JAN. 1931

SIR,

I have the honor to submit, herewith, a statement showing the inspection work of the Great Trigonometrical Survey Stations of this District during the calendar year 1930.

I have the honor to be,

sir,

Your most obedient servant,

For Deputy Commissioner,
Tumkur District.
(Absent from the station).

AD.7/1/31

163.

W D 504—GPB—1,000—23-9-22.

D.4.4]

No. C.Per.101/30-31. OFFICE OF THE DEPUTY COMMISSIONER,
KADUR DISTRICT.

ENC / *Dated Chikmagalur,* 9th January 1931.

FROM

H. V. Ramaswami, Esquire, M.A., B. L.,
Deputy Commissioner,
Kadur District.

To

R. Ranga Rao, Esquire, B.A., B. L.,
Secretary to the Government of Mysore.
- General Department, *Bangalore.*

Sir,

I have the honor to submit herewith, the annual return showing the condition of stations of the Trigonometrical Survey in the Kadur District, for the calendar Year ending 31st December 1930.

I have the honour to be,
Sir,
Your most obedient servant,

Treasury Assistant Commissioner,
For Deputy Commissioner,
Kadur District,
(Absent from Head Quarters).

CB 2424

PP 77-30-7 (25

3PB-

1930-31.

From

M.G.Mehkri, Esquire, B.A., L.L.B.,
Deputy Commissioner,
Shimoga District.

To N.Madhava Rao, Esquire, B.A,B.L.,
Chief Secretary to
Government, BANGALORE.

Dated 13th January 1931.

Despatched

Received

General No. A3. Per. A4./30-31
No.

Enclosure No.

Sir,

With reference to Government order No.2425-92/PP.68-29-27 dated 13-12-30 calling for the submission of the annual report on the condition of the Great Trigonometrical Survey stations in this District, I have the honour to submit herewith the reports in respect of all the survey stations except those in the Sagar Taluk, which will be sent on receipt from the Amildar to whom a reminder has been issued.

2. It is seen from the report of the Assistant Commissioner Shimoga that the Survey station Vemaldigudda No 2991 is almost inaccessible the only way lying through thick jungle full of briars and thorny growths,. There seems to be a great need felt for a bridle path leading to the station . Hence I recommend that a small amount may be sanctioned for this purpose as a special case.

I have the honour to be,
Sir,
Your most obedient servant,

For Deputy Commissioner.

In all future correspondence please quote—
No. L.Dis.A9-C.1316/30-31.
Encls. One statement.

OFFICE OF THE DEPUTY COMMISSIONER,
KOLAR DISTRICT,

Dated, Kolar, the 13th January 1931.

CB-2429
PP 77-30-8

FROM

A. V. RAMANATHAN, ESQ., B.A.,
Deputy Commissioner,
Kolar District.

To

N.Madhava Rao,Esq.,B.A.,B.L.,
Chief Secretary to the Government of Mysore,
B a n g a l o r e.

CHIEF SECRETARY 15 JAN 1931

SIR,

Adverting to your letter No.2788-94/PP.77-30-4 dated 8th January 1931 re: the Annual report of the condition of the Great Trignometrical Survey Stations of this District, I have the honour to forward the same for information.

I have the honour to be,
Sir,
Your most obedient servant,

Deputy Commissioner,
Kolar District.

A.R.13/1/31.

(27

No. C. 1470-30-31

Enc. One

OFFICE OF THE DEPUTY COMMISSIONER,
TUMKUR DISTRICT.

Dated Tumkur, the 13th January *193* 1.

CR. 2430

FROM

G. B. HEBLIKAR, ESQ., B.A., LL.B.,
Deputy Commissioner,
Tumkur District, Tumkur.

pp 77-30-9

To

N. Madhava Rao Esq., B.A., B.L.,
Chief Secretary to the Government of
H. H. the Maharaja of Mysore, Bangalore.

pp CHIEF SECRETARY 15 JAN. 1931

SIR,

In continuation of my letter No.C.1470/30-31 dated 5th January 1931, I have the honour to submit herewith the inspection report of the Great Trigonometrical Survey Station at Pavagada -- inspected by the Sub Division Officer, Madhugiri Sub Division on 31st December 1930 for favour of information.

I have the honor to be,
Sir,
Your most obedient servant,

For Deputy Commissioner,
(Absent from station)
Tumkur District.

No. Per. 11.5/30
Encl. One.

(28

Office of the Deputy Commissioner,
Mysore District.

Dated Mysore, ...15th.January.... *193* 1.

17

C.B.2473
PWD-80-10

FROM

K. V. ANANTHARAMAN, ESQ., B.A.,
Deputy Commissioner,
Mysore District.

To

N.Madhava Rao, Esq., B.A., B.L.,
Chief *Secretary to the Government of Mysore,*
Bangalore.

PP. CHIEF SECRETARY
19 JAN. 1931

SIR,

Annual Report on the condition of Great Trigonometrical Survey Stations in the Mysore District for the year 1930.

-o-

I have the honour to submit herewith the above Annual Report for the year 1930.

I have the honour to be,

Sir,

Your most obedient servant,

K V Anantharamaiah

DeputyCommissioner,
Mysore District.

MGS

CS 247 (29)

In all future communications please quote
No. C6-2244/30-31.
Enc: One report.

Tel. Address.—"DEPCOM"
Post Box No. 84.

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the 16th January *1931.*

PP 77-30-11

FROM

Moin-Ul-Vizarath A.K. Syed Taj Peeran, Esq., B.A.,
Deputy Commissioner,
Bangalore District.

To

N. Madhava Rao, Esq., B.A.,B.L.,
Chief *Secretary,*
to the Government of Mysore.
Bangalore.

CHIEF SECRETARY
17 JAN. 1931

SIR,

Subject:—Re. the annual report on the condition of the Great Trigonometrical Survey Stations in the District.

With reference to your letter No.2788-94/P.P.77-30-4 dated 8-1-1931 re. the above, I have the honour to submit herewith the report on the condition of the Great Trigonometrical Survey Stations in the Bangalore District for the calendar year 1930.

I have the honour to be,

Sir,

Your most obedient servant,

Deputy Commissioner,
Bangalore District.

SS/-.

Tel. Address :—Depcom.
CHITALDRUG.

In reply, please refer to
No. A3. Per. A. 171/30-31.
Enclosures.

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

Dated, Chitaldrug, 16th January 1931.

CB 2493
PP 77-30—

FROM

C. S. KUPPUSWAMIENGAR, Esq.,
Deputy Commissioner,
Chitaldrug District.

CHIEF SECRETARY'S
20 JAN. 1931

N. Madhava Rao Esq B.A.,B.L.,
Chief Secretary to Government,
B A N G A L O R E.

Sir,

With reference to your letter No.2788-94 PP 77-30-4 dated the 8th instant calling for the annual report on the condition of the great Trigonometrical Survey stations in the District for the calendar year 1930 I have the honor to state that the reports have not yet been received from the Amildars of Chitaldrug, Holalkere, Davangere and Harihar. They have been reminded today to expedite the submission of their reports. On receipt of which a consolidated report will be submitted.

I have the honor to be,
S I R,
Yourmost obedient servant

Deputy Commissioner.

AB

Tel. Address :—Depcom.
CHITALDRUG.

In reply please refer to
No. A3...Per.A.171/30-31.
Enclosures. One Sl.

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

Dated, Chitaldrug, 29th January 31 192

PP 77-30-12

FROM

C. S. KUPPUSWAMIENGAR, Esq.,
Deputy Commissioner,
Chitaldrug District.

GENERAL BRANCH 4980 3 FEB. 193

The Chief Secretary to Government,
Bangalore.

Sir,

Subject:- Annual report on the condition of the Trigonometrical Survey station.

With reference to your letter No.2788-94/PP 77-30-4 dated 8th January 1931 on the above subject I have the honor to forward herewith in the prescribed form the annual report on the condition of the several stations in this District for the year 1930.

I have the honor to be,
SIR
Your most obedient servant,

Try: Assistant Commissioner,
For Deputy Commissioner,
Chitaldrug District.
(Absent from station).

(32)

In all future communications please quote
No. C6-2244/30-31. 4992
Enc: -

Tel. Address.—"DEPCOM"
Post Box No. 34.

OFFICE OF THE DEPUTY-COMMISSIONER,
BANGALORE DISTRICT.

4 FEB. 1931
844

Dated, Bangalore, the 2nd February *1931.*

CP 2840

FROM

Moin-Ul-Vizarath A.K. Syed Taj Peeran, Esq., B.A.,
Deputy Commissioner,
Bangalore District.

3 FEB 1931

To

N. Madhava Rao, Esq., B.A.,B.L.,
Chief *Secretary,*
to the Government of Mysore.
Bangalore.

SIR,

Subject:

In continuation of this office letter No.C6-2244/30-31 dated 17th January 1931 forwarding the annual report on the condition of the Great Trigonometrical Survey Stations in the District, I have the honour to forward herewith a copy of the further communication No.O.F.1.(1)/30-31 dated 20-1-1931, received from the Sub Division Officer, Closepet stating that on 16th instant, he made an inspection of the Trigonometrical Survey Station of Savanadurga Hills, and found that the base stone fixed on the station is missing and that it has been removed and destroyed by some mischievous cowherd boys who frequent the place.

In the annual statement for the year ending 31st December 1930 the station is reported to be satisfactory. I request that the information already sent may be kindly caused to be modified so far as this station is concerned.

I have the honour to be,
Sir,
Your most obedient servant,

Deputy-Commissioner,
Bangalore District.

SS/-.

(33)

OFFICE OF THE DEPUTY COMMISSIONER,
SHIMOGA DISTRICT.

No. A3.Per.A4/30-31.

Dated, Shimoga.....24th February.....193 1.

FROM

GULAM MOHADIN MEHKRI, ESQ., B.A, LL.B.,
Deputy Commissioner,
Shimoga District.

To

N. Madhava Rao, Esq., B.A., B.L.,
Chief Secretary to Government,
Bangalore.

GENERAL 5529 26 FEB 945

SIR,

In continuation of this office letter No.A3. Per.A4. 1930-31 dated the 13th January 1931 re: the inspection of the Trignometrical Survey Stations in the District for the calendar year ending 31st December 1930, I have the honor to forward herewith a statement showing the condition of the four stations in the Sagar taluk.

The Amildar explains that he was not able to inspect these stations in time as he was busy in connection with the visits to the Jog Falls of His Highness the Maharaja of Travancore and Prince Jayachamaraja Wadeyar in the months of November and December and that he could not attend to their inspection earlier on account of the rainy season.

I have the honor to be,
Sir,
Your most obedient servant,

Deputy Commissioner,
Shimoga District.

G.M. 07-30-1

WD 2332—GPB—500—5-8-22

D. C. 5]

Office of the Deputy Commissioner,
Kadur District.

No.A7-1846-30/48.
Encl. 1 estimate.

Chikmagalur, dated..... 26th February 1931.

TEMP. CIRCELLANEOUS DEPT. 5580 953.

From H. V. Ramaswami, Esquire, M.A.,B.L.,

DEPUTY COMMISSIONER,
KADUR DISTRICT.

CHIEF SECRETARY 2 MAR 1931

To N. Madhava Rao, Esquire, B.A.,B.L.,

CHIEF SECRETARY TO THE GOVERNMENT OF
HIS HIGHNESS THE MAHARAJA OF MYSORE,
BANGALORE.

SIR,

In submitting herewith an estimate for Rs 4/- for repairing the Trigonometrical Survey Station at Ballalarayandurga in Mudigere Taluk, I have the honour to request that the same may kindly be sanctioned and that the amount of the estimate may be placed at the disposal of the Amildar, Mudigere Taluk, for payment to the contractor.

I have the honour to be,

Sir,

Your most obedient servant,

H. V. Ramaswami
Deputy Commissioner,
Kadur District.

M.N.S.

W.D. C244—GPB—6,00,000—19-5-16—S.

From

The Deputy Commissioner,

Kadur District.

To

The Chief Secretary to

the Government of His Highness

the Maharaja of Mysore,

Dated Bangalore.

Despatched

Received

General No.

No.

Enclosure No.

SUBJECT

Estimate for the repairs of the Trignometrical Survey Station (35)
at Bālālarāyanadurga - Durgadahalli Village. Balur Hobli
Magadi Taluk 30-31.

No	Description	No.	Contents	per	Rate	cost	Total.
1	Jungle clearing in bits on the platform. (Shri)	1	1		2 - -	2 - -	
2	planting one pillar at the station. (Sarala - ganika Wood)	1	.	.	2 - -	2 - -	4 - -
			For Rupees four only				

Ths Krishnaiah
R.I. Balur
10/2/31

Ramachandra
Amildar
12/2/31

G.M.101-30-2.

(36)

In all future communications please quote
No. 06-3269/30-31
Enc: One.

Tel. Address.—"DEPCOM"
Post Box No. 84.

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the 7th April *193* 1.

SECRETARIAL MISCELLANEOUS 6380 9 APR 1931

FROM

K.V. Anantaraman, Esq., B.A.,
Deputy Commissioner,
Bangalore District.

CHIEF SECRETARY. 11 APR. 1931

To

N. Madhava Rao, Esq., B.A.,B.L.,
Chief *Secretary,*
to the Government of Mysore.
Bangalore.

SIR,

Subject:—

X-R

With reference to your letter No.G.M.A. 70/G.M. dated 2-4-1931, calling for an estimate of the cost of repairs to the Hill station, Savanadurga, No.326 and other particulars, I have the honour to forward herewith a copy of Closepet Sub Division Officer's letter No.O.P.1 (1) 30-31 dated 20-1-1931 and to state that the Sub Division Officer has been directed to get an estimate of the cost of repairs to the hill station, Savanadurga No. 326 and submit the same early. He has been reminded again in the matter and on receipt of his reply, a further communication will be made to you in the matter.

As regards the dates of inspection of the marginally noted hill stations, no information is forthcoming in the reports of the Sub Division Officers of Dodballapur and Closepet Sub Divisions. But the Sub Division Officer, Bangalore, has reported that he has inspected the Bangalore Base Line N E End S on 20-7-1930. The two other Sub Division Officers are requested to submit a report in the matter before the 10th of this month after which date, a final communication will be made to you in the matter.

1. Halasur Betta
2. Kalkote
3. Koppabetta
4. Makalidurga
5. Savanadurga

I have the honour to be,
Sir,
Your most obedient servant,

K. Anantaraman
Deputy Commissioner,
Bangalore District.

SS/-.

(37)

Letter No.O.P.1 (1) dated 20-1-1931 from the Sub Division Officer, Closepet, to the Deputy Commissioner, Bangalore Distt.

I have the honour to state that I inspected the Trigonometrical survey station on Savandrug Hills, Magadi taluk, in company with the Amildar on the 16th instant and found that the base stone fixed on the station is missing. In the annual statement for the year ending 31st December 1930, it is noted, that the station is reported to be in good condition If my report has not been sent up already, this revised report may be substituted for it.

If despatched, a further communication may now be made to the authorities concerned. It is reported that the stone was intact when the Amildar visited it last. But that it has been removed and destroyed by some mischievous cowherd boys who frequent the place. I have issued orders to the Amildar to trace the stone and refit it on the pedestal as early as possible; but from the search caused to be made by me, the attempt appears to be futile.

"Copy"

For Deputy Commissioner,
Bangalore District.

SS/-.

G.M. 101-30-3 (38

No. C. 1470/30-31

Enc. Sri 1.

OFFICE OF THE DEPUTY COMMISSIONER,
TUMKUR DISTRICT.

Dated Tumkur, the 8th April *1931.*

FROM M. Sadasiva Rao Esq., B.A., B.L.,
~~G.C.B.I. HERLIKAR, Esq. B.A. LL.B.~~
Deputy Commissioner, in charge
Tumkur District, Tumkur.

To
H. Madhava Rao Esq., B.A., B.L.,
Chief Secretary to the Government of
H. H. the Maharaja of Mysore, Bangalore.

GOVT. SECRETARIAT 13 APR. 1931

6476 1104

SIR,

With reference to your letter No.G.10068/G.M. dated 2-4-1931, calling for a copy of my letter No.C.1470 dated 13th January 1931 re: the inspection report of the Great Trigonometrical Survey Station at Pavagada, I have the honour to forward herewith the same and to state that the Inspection report of the Trigonometrical Station at Pavagada made by the Sub Division Officer, Madhugiri Sub Division on 31-12-30 was sent in original with the letter referred to above. Such being the case a copy of the same cannot be sent

I have the honor to be,

Sir,

Your most obedient servant,

Deputy Commissioner in charge
Tumkur District.

T.M.C. 8/4

(31)

OFFICE OF THE DEPUTY COMMISSIONER,
SHIMOGA DISTRICT.

No. A3..A4/30-31.

Dated, Shimoga.....14th April.....1931.

FROM

GULAM MOHADIN MEHKRI Eso. BA, LLB
Deputy Commissioner,
Shimoga District.

GENERAL 6539 1447 16 APR. 1931

To

N. Madhava Rao, Esq., B.A., B.L.,
Chief Secretary to Government,
Bangalore.

CHIEF SECRETARY'S 16 APR. 1931

SIR,

With reference to your letter No,G. 10066 G.M. dated 2nd April 1931, I have the honor to note on the margin* the name and rank of the Inspecting Officers and the date of inspection of the Hugadi and Kalavarangan Trignometrical survey stations in the district.

I have the honor to be,
Sir,
Your most obedient servant,

For Deputy Commissioner,
Shimoga District.

*

No.	Name of station.	Date of Inspection.	Name and rank of Inspecting officer.
1.	2984 Hugadi (Nagar taluk)	27-12-1930.	Mr. C.N. Gopalaswami Naik, Amildar, Nagar taluk.
2.	2985 Kalavarangan (Honnali taluk)	25-12-1930.	Mr. B. Rachappa, Amildar, Honnali taluk.
3.	2986 Kalingarayan (Channagiri taluk)	20-12-1930.	Mr. K. Subba Rao, Amildar, Channagiri taluk.

NP.

(4)

Appendix F G—1

SUBJECT.....

.....

.....

Section G.M.

File No. 101-30

Serial No. 4

No. G.10692/Enl.

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the *193* .

To The D.C. Tumkur.

.....

Date of issue 23/4/31

Signed by Mr. N.D. Rao

List of enclosures.....

Copied by.....

Examined by.....

Sir,

With reference to your letter No. 1470/30-31 dated 8-4-1931 forwarding a copy of your letter No. C 1470 dated 13-1-1931, I am directed to invite your attention to this office letter No. 10068/G.M. dated 2-4-1931 calling for a copy of your letter No. C 1470/30-31 dated 5-1-31, and not the one dated 13-1-31 which you have sent now, and to request you to send the letter dated 5-1-1931 immediately. A copy of the letter dated 13-1-31 is returned herewith.

I have the

over

WD 02559—GPB—25,000—25-6-30

for Chief Secretary

17/4

Tel. Address :—Depcom.
CHITALDRUG.

In reply, please refer to
No. A.D.L.C. 1757/30-31
Enclosures:

G.M. 101-30-5.

41

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

Dated, Chitaldrug, 18th April 1931 *192*

FROM M. Seshadri Esq M.A.,
C.S. KUPPUSWAMY, ESQ.
Deputy Commissioner,
Chitaldrug District.

DEPUTY COMMISSIONER 6606 21 APR 1931 CHITALDRUG

CHIEF SECRETARY, 20 APR. 1931

N. Madhava Rao Esq B.A., B.L
Chief Secretary to Government,
B A N G A L O R E.

Subject:- Report on the condition of Trigonometrical Survey stations.

Sir,

With reference to your letter No.G.10069/G.M. dated 2nd April 1931 requesting to report on the condition of Guheswaragudda and Jogimatti stations &c. I have the honor to forward herewith an estimate for Rs 10 received from the Amildar Chitaldrug for effecting repairs to the Jogimatti station. The Amildar reports that Guheswaranagudda station was not inspected by him during the year 1930 but that the jogimattir station was inspected by him on 19th January 1930.

I have the honor to be,
S I R,
Your most obedient servant,

M. Seshadri
Deputy Commissioner.

Estimate of the probable cost of Repairing the Trignometrical Survey Station at Jagimatti in Chitaldroog Dalug. (42)

Details of work	No	Dimensions L	B	D	Contents/Total	Rate Rs	a	p	Cost Rs	a	p
Removing the old dilapidated Brick in mortar walls & covering with new Berat Brick in mortar & arranged the platform	1	40	3/4	3/8	11 Cft.		8			6	
Chanam plastering to the above walls & also platform & also pevered in the centre			L.S.		1 Sqr	4			4		
Total									Rs 10		0

A. Ramanna
Surveyor

A. Ameer
Overseer

13 4 31

Report to accompany the Estimate.

This is an Estimate for Repairing the Trignametrical Survey Station at Jogimatti in chitaloor Taluq.

The Trignometrical Survey Station at Jogimatti is very badly in need of urgent Repairs. The Brick in mortar wall around the platform is in a Dilapidated Condition. The central portion of the platform also pedestal in the middle Require Cheneam plastering. Necessary provisions is made for all urgent Items. Duplicates of Estimate are Submitted for kind perusal & Sanction.

K. Rama Rao
Asst. Engr.

D. 12.4.31.

G.M. 101 — 30 - 6.

(46)

In all future correspondence please quote this
No. AS-C-2159/30-31.
Encls. One Estimate.

OFFICE OF THE DEPUTY COMMISSIONER,
KOLAR DISTRICT.

Dated, Kolar, the 16th April *1931*

FROM

A. V. RAMANATHAN, ESQ., B.A.,
Deputy Commissioner,
Kolar District.

To
N.Madhava Rao,Esq.,B.A.,B.L.,
CHIEF SECRETARY TO GOVERNMENT OF MYSORE,
~~Department~~,
Bangalore.

GENERAL MISCELLANEOUS BRANCH 6617 21 APR. 31

CHIEF 2 APR. 1931

SIR,

With reference to your letter No.G.10067/G.M. dated 2-4-1931, calling for the submission of the estimates of the cost of repairs to the Bhupatamma and Yerrakonda, Trigonometrical Stations, I have the honour to submit herewith an estimate for Rs 10/- being the probable cost of repairs to the station of Bhupatammabetta, as the platform requires replastering with Surki mortar and resetting of stone revetment of the steps.

As regards the estimate for Yerrakonda the Amildar of Bowringpet Taluk has been addressed to send one and the same will be sent to you on receipt. A reminder has this day been issued to the Amildar to expedite the matter.

I have the honour to be,
Sir,
Your most obedient servant,

Deputy Commissioner,
Kolar District.

A.R.2.
16/4/31.

Estimate of the probable cost of Repairs to the Hill station of Bhupathamma betta.

No	Details of work	Quantity	Mate	Hmamt
1.	Replastering the platform with Surki mortar and resetting the stone pavement of the platform & some plates of the steps to the station		Lumpsum.	
			10 . .	10 . .
				10

Contingent Proof (Deo only)

Rupees ten only.

Deo only

Approved

Nagamanda
Builder
Kadur Taluk.
14.4.31

G.M.101-30-7

(44)

In all future communications please quote
No...C6-3269/30-31.
Enc One.

Tel. Address.—"DEPCOM"
Post Box No. 34.

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the ....22nd..April.....*1931*.

FROM

K.V.Anantaraman, Esqr., B.A.,
Deputy Commissioner,
Bangalore District.

GENL. 6688
24 APR 11.45 A

TO THE HON'BLE
MYSORE
23 APR. 1931

N.Madhava Rao, Esqr., B.A., B.L.,
Chief Secretary,
to the Government of Mysore.
BANGALORE.

SIR,

Subject:—

In continuation of this office letter No.C6-3269/30-31 dated 8-4-31 answering certain points raised by you in your letter No.G.100701/Gol dated 2-4-31, I have the honour to forward herewith a copy of Closepet Sub Division Officer's letter No.O.P.No.1 (1) 30-31 dated 10-4-31 and to state that that the great trigonometrical stations at Kotekpppe and Savandurga are reported to have been inspected by the present Sub Division Officer Mr.Dwarakanath, B.A.,B.L.,on 9-12-30 and on 16.1.31, respectively, and that as the base stone is lost, the Sub Division Officer requests to be informed as to whether the estimate to be submitted is for fixing a stone slab or the stone has to be fixed by the Survey of India Party after due verification. I request that instructions may be given in the matter. Re. the dates of inspection of the hill stations at Halasur Betta, Kallkote and Makali durga, Mr.Hukh who is stated to have inspected the stations has been asked to furnish the information required. On receipt of his reply a further communication will be made to you in the matter.

I have the honour to be,
Sir,
Your most obedient servant,

For Deputy Commissioner,
Bangalore District.,
(Absent from station).

Letter No.C.P.No.1.(1)/30-31 dated 10th April 1931 from the Sub Division, Closepet Sub Division to the Deputy Commissioner, Bangalore District.

(47)

With reference to your MemoNo.C.6-3269/30-31 dated 7th April 1931 regarding the estimate of the cost of repairs to the Hill Station, Savandurga, No.326 and other particulars, I have the honour to state that the base stone is lost and attempts to trace it has been futile and instructions may be issued if the estimate is for fixing a stone slab and whether the stone has to be fixed by the Survey of India Party after due verification. If the reply is that we can do it then I will ask the Assistant Engineer to get up and estimate very early.

Kottekoppa on 9-12-30 / Savandurga on 16-1-31. } But as regards the dates of inspection of the station, the same were inspected on the dates noted in the margin.

"C o p y."

For Deputy Commissioner,
Bangalore District.

G.M.101-30-8. 48.

In all future correspondence please quote this No. L.Dis.A.3.C.2159/30-31 Encls.

OFFICE OF THE DEPUTY COMMISSIONER,
KOLAR DISTRICT.

*Dated, Kolar, the...*22nd April 1931.*19*

FROM

A. V. RAMANATHAN, ESQ., B.A.,
Deputy Commissioner,
Kolar District.

6694
24/4/31

To

N.Madhava Rao, Esq., B.A., B.L.,
SECRETARY TO GOVERNMENT OF MYSORE,
Department,
Bangalore.

OHIE... 24 APR. 1931

SIR,

With reference to your letter No.G.10067/G.M.2-4-31 calling for the submission of estimates of the cost of repairs to the Hill Stations of Bhupatamma No.1941 and Yerrakonda No.1949, I have the honor to submit herewith an estimate of the probable cost of repairs to the Hill Station of Yerrakonda No.1949 amounting to Rs.5/- as desired.

An estimate of the cost of repairs to Bhupatamma Hill Station was already submitted with this office No.A.3.C.2159/30-31 dated 17th April 1931.

I have the honor to be,
Sir,
Your most obedient servant,

A.V. Ramanathan
Deputy Commissioner,
Kolar District.

(119)

Gl. 12032 & 12048
1930-31
IMMEDIATE.

ವಿವರಂಚನೆಯಲ್ಲಿ ಕಾಲ್ಪನಿಕ ತಪ್ಪೆಲಾಯಿತು

ಬೇತಮಂಗಲದ
(ಕಾವಲುದಂಬಳ್ಳಿ)ದಿಬ್ಬಾಲಳ್ಳಿ ತಿಗಳ್ಳರ್ ಅಂಜನಪ್ಪನವರ ದೂರು.

ದಿ ಕೋಲಾರ ಹಳೆ ತಿಪ್ಪಸಂದ್ರ ಅಗ್ರಹಾರದ ಅಡ್ಡೆಸ್ವಾಮಿಯವರ ತಿಗಳರ ಸಂಪ್ರದಾಯದಂತೆ ಕಾವಲುದಂಬಳ್ಳಿ ದಿಬ್ಬಾಲಳ್ಳಿ - ಬಾಸಪಲಿಯಳ್ಳಿ ಎಂಬ ಕಡೆಗಳಲ್ಲಿ ಸತ್ತವರನ್ನು ಹೂಳುವ ಸ್ಮಶಾನದಲ್ಲಿ ಸುಮಾರು ೨೦ ವರ್ಷಗಳಿಂದ ಹೂಳುತ್ತಾ ಬಂದಿರುವುದಾಗಿಯೂ ಈಗ ಸುಮಾರು ೨ ತಿಂಗಳ ಹಿಂದೆ ಸತ್ತ ಒಂದು ಹೆಣವನ್ನು ಹೂಳಲು ಹೋದಾಗ ಅಲ್ಲಿ ಹೂಳಲು ಬಿಡದೆ ಅಡ್ಡಿಪಡಿಸಿದ್ದರಿಂದ ಹೆಣವನ್ನು ಹಾಗೆಯೇ ಬಿಟ್ಟು ಬಂದಿರುವುದಾಗಿಯೂ ಆದ್ದರಿಂದ ಈ ಸ್ಮಶಾನವನ್ನು ಮುಂದೆ ಹೂಳಲು ಅನುಕೂಲವಾಗುವಂತೆ ಮಾಡಿಕೊಡಬೇಕೆಂದು ಕೋರಿ ಅರ್ಜಿ ಸಲ್ಲಿಸಿರುವುದರಿಂದ ಈ ವಿಷಯವಾಗಿ ವಿಚಾರಣೆ ಮಾಡಿ ವರದಿ ಮಾಡಲು ಆಜ್ಞೆಯಾಗಿದೆ - ಆದ್ದರಿಂದ ಅರ್ಜಿದಾರರನ್ನು ಮತ್ತು ಎದುರುದಾರರನ್ನು ~~ಕರೆಯಿಸಿ~~ ವಿಚಾರಣೆ ಮಾಡಿ ~~ಆಜ್ಞೆಯಾಗಿದೆ~~ ದಿನಾಂಕ 30-14-4-31ಕ್ಕೆ ಕಛೇರಿಗೆ ಕಳುಹಿಸಿಕೊಡಲು. ಅಲ್ಲಿಯವರೆಗೂ ಯಾವ ವಿಧವಾದ ಕ್ರಮವನ್ನೂ ತೆಗೆದುಕೊಳ್ಳಬಾರದು - ಅಲ್ಲಿಯವರೆಗೂ ಸ್ಮಶಾನವನ್ನು ಉಪಯೋಗಿಸಲು ಅಡ್ಡಿಪಡಿಸಬಾರದು - ಎಂದು ಆಜ್ಞೆಯಾಗಿದೆ. ಆದ್ದರಿಂದ ಈ ವಿಷಯವಾಗಿ ನಿಮಗೆ ತಿಳಿಸಿದ್ದನ್ನು ಅಂದು ತಿಳಿಸಿರುವುದಾಗಿ ಆಜ್ಞೆಯಾಗಿದೆ.

H. Ghimappa
Amildar
Bowringpet Taluk
13/4/31.

ಕಛೇರಿಯಲ್ಲಿ ಬಳಸಲು

ಕೋಲಾರ ಜಿಲ್ಲಾ ಕಛೇರಿಯಲ್ಲಿ ಸ್ವೀಕರಿಸಿದ ದಿನಾಂಕ ಮತ್ತು ಸಂಖ್ಯೆ

A3 IN THE DEPUTY COMMR'S OFFICE 8 APR. 1931 G. No. A2 2264/6 Gl. 12032-12048/30-31

ಸಹಾಯಕ ಕಂದಾಯ ಅಧಿಕಾರಿಗಳ ಕಛೇರಿಯಲ್ಲಿ ಸ್ವೀಕರಿಸಿದ ದಿನಾಂಕ

16.4.1931

Kondaba Raju
Rev. Inspector

ಬೇತಮಂಗಲದ ಕಾವಲುದಂಬಳ್ಳಿ ದಿಬ್ಬಾಲಳ್ಳಿ ತಿಗಳರ್ ಅಂಜಿನಪ್ಪನವರ ಸ್ಮಶಾನ ವಿಚಾರಣೆಗೆ ಸಂಬಂಧಪಟ್ಟ ವರದಿಯನ್ನು ಕಳುಹಿಸಿಕೊಡಲಾಗಿದೆ.

ವಿವರಂಚನೆಯಲ್ಲಿ ಕಾಲ್ಪನಿಕ ತಪ್ಪುಗಳಾಗಿರುವುದಿಲ್ಲ.

R1 15/4/31 ಸಹಾಯಕ ಕಮೀಷನರ್ ಅವರ ಜ್ಞಾಪಕ ಪತ್ರ ದಿನಾಂಕ 12-4-31 ಕೋಲಾರ ಜಿಲ್ಲಾ ಕಛೇರಿ ಸಿ. ಪಿ. ಸಂ. 28/30-31 - ಈ ವಿಷಯವಾಗಿ ಅರ್ಜಿದಾರರಾದ ಅಂಜಿನಪ್ಪನವರನ್ನು ಮತ್ತು ಎದುರುದಾರರನ್ನು ಕರೆಯಿಸಿ ವಿಚಾರಣೆ ಮಾಡಿ ವರದಿಯನ್ನು ಕಳುಹಿಸಿಕೊಡಲು ಆಜ್ಞೆಯಾಗಿದೆ. ಆದ್ದರಿಂದ ಅರ್ಜಿದಾರರಾದ ಅಂಜಿನಪ್ಪನವರನ್ನು ಮತ್ತು ಎದುರುದಾರರನ್ನು ಕರೆಯಿಸಿ ವಿಚಾರಣೆ ಮಾಡಿ ವರದಿಯನ್ನು ಕಳುಹಿಸಿಕೊಡಲಾಗಿದೆ.

R1 18 APR. 1931 8990. ASSISTANT COMMISSIONER KOLAR SUB-DIVISION.

C. P. No. 28/30-31 ರ ಕೇಸಿನಲ್ಲಿ ಸಂಬಂಧಪಟ್ಟವರಿಗೆ ಜ್ಞಾಪಕ ಪತ್ರಗಳನ್ನು ಕಳುಹಿಸಿಕೊಡಲಾಗಿದೆ.

Submitted to the Dy. Comr., Kolar Dt.
in Continuation of this Office No. C. Pr. 28/30-31
dt 15-4-31 & with reference to this No. A3-C. 1316/30-31
dt 14-4-31.

Appamakkle
15/4/31 Asstt. Comr., Kolar Sub-Div.

H. Ghimappa
Amildar
Bowringpet Taluk
16/4/31

Estimate of the probable cost of petty repairs to the Hill Stations of Yerrakonda for 1949 in the Taluk of Bowringpet for 1930-31. 50

Rp	Details of work	No.	Dimensions L.	B	D	Contents	Rate	Cost
I	Patching up of destroyed portions (here & there) with burnt bricks in chunam in the foundations and Constructions		L. S.				£. S.	3 8.
II	Chunam plastering and white washing Hill Stations complete		L. S.				£- S	1 8.
	Total							5 . .

Rupees Five only ——

Kamba Raju,
Rev. Inspector,
Kyasamballi Hobli

M. 16. 4. 1931

Rupees Five only

Abbinappa
amildar

8/8
16/4, Bowringpet taluk

Immediate

No. C. Per. 28/30-31.

(57)

Memo

Forwarded to the Amildar, Bowringpet Taluk, for immediate submission of the estimate called for in respect of Yerrakonda H.S.C Byatarayankalli No. 1949 overleaf. He will please arrange to send on the estimate muddam so as to reach this Office on the 13th instant without fail. The matter should be treated as very urgent

Sd. Assistant Commissioner
Kolar Sub Div
12/4/31.

P.
Heerolee
13.4.31.

4:1/2032.

G.M. 101-30-9.

(52)

Tel. Address :—Depcom.
CHITALDRUG.

In reply, please refer to
No. A3.C.1948/30-31
Enclosures.

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

Dated, Chitaldrug, 28th April 31. 192

FROM

M. SESHADRI, Esq., M.A.,
C. S. KUPPUSWAMI ENGAR, Esq.,
Deputy Commissioner,
Chitaldrug District.

6769
1157

To

CHIEF SECRETARY.
28 APR. 1931

N. MADHAVA RAO, Esq., B.A., B.L.,
Chief Secretary to Government,
B a n g a l o r e.

Subject:- Repairs to the Trigonometrical Survey Station at Jogimatte, Chitaldrug Taluk.

Sir,

In continuation of this office No. A3.L.C. 1757/30-31 dated the 19th instant forwarding an estimate for Rs 10/- for effecting repairs to the above named station, I have the honour to state that as the Forest Lodge at Jogimatte is now under repairs, a copy of the estimate forwarded to you has been sent to the Amildar of Chitaldrug for getting the necessary repairs done to the Trigonometrical Station within the estimated cost pending sanction of the estimate.

I request that my action may kindly be approved.

I have the honour to be,
Sir,
Your most obedient servant,

SRS/28-4

M Seshadri
Deputy Commissioner,
Chitaldrug District.

G. M. 101-30-40.

WD 2332—GPB—500—5-6-22

53

D. C. 5]

No.A7-1846-30/48.

Office of the Deputy Commissioner,
Kadur District.

Chikmagalur, dated 24th April 1931.

From C. S. Kuppuswamiengar, Esquire,
DEPUTY COMMISSIONER,
KADUR DISTRICT.

CENTRAL CHANCELLERY RECD. 6747 27 1155

CHIEF SECRETARY 27 APR. 1931

To

N. Madhava Rao, Esquire, B.A., B.L.,
CHIEF SECRETARY TO THE GOVERNMENT OF
HIS HIGHNESS THE MAHARAJA OF MYSORE,
BANGALORE.

SIR,

In inviting your kind reference to this office No.A7-1846-30/48 dated 27-2-1931 submitting an estimate for Rs. 4/- for repairing the Trigonometrical Survey Station at Ballalarayandurga in Mudigere Taluk, I have the honour to request that the estimate may kindly be returned duly sanctioned as the repairs are to be executed before the commencement of the monsoon season.

I have the honour to be,
Sir,
Your most obedient servant,

Treasury Assistant Commissioner,
For Deputy Commissioner,
Kadur District.

(Absent from Head Quarters)

M.N.S.

W.D. 0244—GPB—6.00,000—19-5-16—S.

From

The Deputy Commissioner,
Kadur District.

To

The Chief Secretary to
the Government of His Highness
Dated the Maharaja of Mysore,
Despatched Bangalore.

Received

General No. _____
No.

Enclosure No.

SUBJECT.

(54

No. C.1470/30-31

Enc. 2

OFFICE OF THE DEPUTY COMMISSIONER,
TUMKUR DISTRICT.

Dated, Tumkur, the 8th May *193*1.

FROM H.V. Ramaswami Esq., M.A., B.L.,
~~G.V.K. Hebbar, Esq., B.A., B.L.,~~
Deputy Commissioner,
Tumkur District, Tumkur.

G.M. 7053
- 120

To

N. Madhava Rao Esq., B.A., B.L.,
Chief Secretary to the Government of H. H.
the Maharaja of Mysore, Bangalore.

SIR,

With reference to your letter No.G.10692/G.M.101-30-4 dated 23rd April 1931, I have the honour to forward herewith a copy of my letter No.C.1470/30-31 dated 5/7th January 1931 together with a copy of its enclosure as called for, for favour of your information.

I have the honor to be,

Sir,

Your most obedient servant,

For Deputy Commissioner,
Tumkur District.

T.M.C. 8/5

(5)

Copy of letter No.C. 1470/30-31 dated 5/7th January 1931, from the Deputy Commissioner, to the Chief Secretary to Govt: of Mysore.

--00--

"

I have the honor to submit herewith a statement showing the Inspection work of the Great Trigonometrical Survey stations of this District during the calendar year 1930. "

--00--

COPY

For Deputy Commissioner,
Tumkur District.

AD. 8/5

4	5	6		
Pargana, Taluka, Thana	Names of nearest villages	Condition of station and estimated cost of repairs		Name & rank of Inspecting officer & date of Inspection
Tipleg Taluk	Godabanahalli, Guladahalli Bommanahalli and Hosa halli	Good	-	6. Lakshmana Rao BA, BL Sub Division Mysore Sub-Divisional Officer 17-7-1930
Sohegini Taluk	Settihalli, puttanahalli and Soganahalli	Good	-	Mr M. puttaswami Amildar Madhugiri 30-12-1930
Tiptur Taluk	Bhandanahalli, Krishnapura Doddenahalli and Turuvekere	Reports that it was recently repaired & is in good condition.	Mr - Mr 27-12-30.	M. Venkatapurisetti BA By Amildar Turuvekere 18-12-30 Lakshmana Rao Sub-Division Officer Tiptur Sub-Division
Sukere Taluk	Anapanahalli, Thimma-naikanahalli and Durgadahalli	Inspected by Good Mr K. Ramaswamy Taluk Shr 25-12-30 Sub-division Officer Tumkur Sub-division 25-12-30.	Mr 21-1-30	G. B. Hebbikar BA Revenue 21-1-30. A. L puttaiya Amildar Tumkur 21-1-30 & 29-4-30.
Sohegini Taluk	Thimmalapura and Kavanadala	Good	-	Mr M. puttaswami Amildar Madhugiri 29-12-1930.
Gubigal Taluk	Huliyurdurga, Ujini, Hettapur and Varadarajanapalya	Good	-	Mr B. P Sarafa BA LLB Amildar Gubigal 28-12-30
Pavagada Taluk	Pavagada and Rangapura	Reports that the pyramid is damaged on the sides & also on the top & that it is to be repaired & whitewashed	Rs 10	Mr P. K. Doreswami Iyengar BA Amildar Pavagada 24-12-1930.
Sukere Taluk	Basavapatna, Kari-Kalpalya, Boorunga-nabadapalya and Siddagangemutt	Good	-	Mr A. L puttaiya Amildar Tumkur 30-12-1930
Gubigal Taluk	Kunigal, Nesamarinpur Kalaganapalya and Bommadagiri.	Good	-	Mr B. P. Sarafa BA LLB Amildar Kunigal 25-12-1930
Tiptur Taluk	Sitakallu gudda, Sitakallu Kalenahalli, and Gujjiganahalli.	Reports that the pedestal of the benchmark is damaged & requires repairs.	Rs 20	Mr L. Munisami BA Amildar Koratagere 13-11-1930

(Sd) G. B. Hebbikar
Deputy Commissioner
Tumkur District

Commissioner
District
1/4/31

1/5/31

	1	2	3	
	Survey name of station	Local name of station	Village in which the station lies	Tahsil.
3406	Bommanahalli H. S.	Bommanahalli Betta	Bommanahalli	
3407	Byal H. S.	Baillippibetta	Byalya	
3408	Chandankalli. S.	Krishnapura	Between Bhamana halli and Krishnapura	Dep
3409	Devarayadurga H. S.	Devarayadurga Betta.	Devarayadurga	D
3410	Dodnirmanya H. S	Dodnirmanya	Karanadala	Ma
3411	Hemagiri H. S.	A Hill near Rangaswamibetta and Hutridurga Betta	Hutridurga	K
3412	Paragada H. S.	Sultanbateri	Paragada	P
3413	Ramadevarabetta H. S.	Ramadevarabetta	Basavapatna Immediate Salute	Im
3414	Rangaswamibetta H. S	on the West of the Hutridurga Hill and Kunigal	Kothagiri and Kunagra	Ku
3415	Sitakal H. S.	Ramadevarabetta	Sitakallu	Im

Corrig

For depu
by Boy

(57)

In all future communications please quote
No. C6-3269/30-31.
Enc two.

Tel. Address.—"DEPCOM"
Post Box No 34

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the 26th May 1931.

FROM K. V. Anantaraman, Esq., B.A.,

Deputy Commissioner,
Bangalore District.

To N. Madhava Rao, Esq., B.A., B.L.,

Chief *Secretary,*
to the Government of Mysore.

SIR,

Subject:—

In continuation of this office letter No.C6-3269/30-31 dated 21-4-1931 forwarding a copy of Closepet Sub Division Officer's letter No.O.P.No.1(1)/30-31dated 10-4-1931 regarding the inspection of great Trigonometrical stations, I have the honor to forward herewith the letter received from Mr. Abdul Hukh, Sub Division Officer, Bangalore and to state that he was unable to inspect the hill stations in question for reasons set forth in his report.

I have the honor to be,

Sir,

Your most obedient servant,

K. V. Anantaraman

Deputy Commissioner,
Bangalore District.

P.R.M.

Ref:- Dy Commr's No C6-3269
dt 10.4.31 (5830/31

For PR 55/31.
29/4 Submitted to the Deputy Commissioner

I was not able to inspect Makalidurg Trigonometrical Station on account of other engagements and my transfer order of December last. The Trigonometrical Station was inspected however by the amildar who has reported that the Trigonometrical Station was in a good condition. This reference could have been easily available to my successor if he had cared to look into it.

Mahrelltable
Sub-Division officer
Bangalore Sub Dy

23/4/31.

52246

DEPUTY COMMISSIONER'S OFFICE
29 APR 19[illegible]
No. C6
BANGALORE DIST.

(59

In all future communications please quote
No. CC-3269/30-31.
Dne.

Tel. Address, "DEPCOM"
Post Box No. 34.

OFFICE OF THE DEPUTY COMMISSIONER,
BANGALORE DISTRICT.

Dated, Bangalore, the 7th April *1931.*

FROM K.V. Anantaraman, Esq., B.A.,
Deputy Commissioner,
Bangalore District.

To N. Madhava Rao, Esq., B.A., B.L.,
Chief *Secretary,*
to the Government of Mysore,
Bangalore.

SIR,

Subject:—

With reference to your letter No.G.M.A. 70/G.M. dated 2-4-1931, calling for an estimate of the cost of repairs to the Hill station, Savanadurga, No.326 and other particulars, I have the honour to forward herewith a copy of Closepet Sub Division Officer's letter No.U.P.1 (1) 30-31 dated 20-1-1931 and to state that the Sub Division Officer has been directed to get an estimate of the cost of repairs to the hill station, Savanadurga No. 326 and submit the same early. He has been reminded again in the matter and on receipt of his reply, a further communication will be made to you in the matter.

As regards the dates of inspection of the marginally noted hill stations, no information is forthcoming in the reports of the Sub Division Officers of Dodballapur and Closepet Sub Divisions. But the Sub Division Officer, Bangalore has reported that he has inspected the Bangalore Base Line N E End S on 20-7-1930. The two other Sub Division Officers are requested to submit a report in the matter before the 10th of this month after which date, a final communication will be made to you in the matter.

1. Halasur Betta
2. Kalkote
3. Koppabetta
4. Makalidurga
5. Savanadurga

I have the honour to be,
Sir,
Your most obedient servant,

Sd/-K.V. Anantaraman,

Deputy Commissioner,
Bangalore District.

SS/-.

p.t.o.

Copy of the foregoing is forwarded to the Sub Divisional Officer, Bowringpet, for submission of a report mentioning the dates on which the hill stations at Bettahalasur, Kamate, Kallugopalpet were inspected, before the 10th of this month.

for Deputy Commissioner,
Bangalore District.

DEPUTY COMMISSIONER'S OFFICE
Cb
10 APR 31
Rs.....
Bangalore

A27(4)11-1 30-31 3005-8

I beg to report that the report of Inspection of 16 Trigonometrical stations was submitted by my predecessor in office ~~by~~ Mr. Abdul Hakeem I took charge of this office on 31st. Dec. 1930. It is seen from the office draft that Mr. Abdul Hakeem did not himself inspect ~~the~~ The hill station mentioned in the letter under reference and he does not seem to have inspected the station at Kanmur also, but relied on the reports of the Amildars in the matter which are not available. Under these circumstances it is not possible for me to give the dates of these inspections.

G. Rudrappa
Sub Division Officer
Wood Kallugopalpet Sub

Cb 3-69/30-31
by 8/4/31.

Forwarded with Compliments to Mr. Abdul Hakeem for furnishing the information required.

for By Comm
10/4/31

Secretariat
Bring up for reply
S/4

Tel. Address :—Depcom.
CHITALDRUG.

Gpm 107-30-11

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

(61)

In reply, please refer to
No.....A3..Per.A.171/30-31. *Dated, Chitaldrug,...22nd..June...1931*192.
Enclosures. One statement.

GENERAL SECTION 7903 24 JUNE 1931 SECRETARIAT

FROM M. Seshadri, Esq., M.A.,
C.S. KUPPUSWAMI ENGAR, Esq.,
Deputy Commissioner,
Chitaldrug District. 1286

OFFICE OF THE CHIEF SECRETARY TO GOVT. 24 JUNE 1931 BANGALORE

To

N, Madhava Rao, Esq., B.A., B.L.,
Chief Secretary to Government,
B A N G A L O R E .

Subject: Inspection of Trigonometrical stations for the year 1930.

--: O :--

Sir,

With reference to your letter No. G. 12269 dated 15th June 1931 calling for information about the name and rank of officers who inspected the stations etc., I have the honour to enclose herewith a statement showing the information required.

I have the honour to be,
S i r ,
Your most obedient servant,

Treasury Assistant Commissioner,
For Deputy Commissioner,
absent from Head-quarters.

Statement showing the name and rank of the officers who inspected the Trigonometrical Stations and also the date of inspection in the Chitaldrug district for the year 1930.

Sl. No.	Trigonometrical Stations	~~Date of inspection~~ Name & rank of the officers who inspected the Stations.	Date of inspection	Remarks.
1	Guheswaranagudda	———	———	It is reported that the Amildar, Chitaldrug did not inspect the station in 1930.
2	Jogimatti	Amildar, Chitaldrug Mr. M. Venkatasubba Rao	19-1-30	
3	Hottegudda	Amildar, Holalkere now K. Gundu Rao	27-11-1930	
4	Shigekal Station	S.D.O. Davangere Mr. T. Ramiah	22-7-30	
5.	Bathigudda M.S.	Amildar Davangere Mr. K. Madhava Rao	21-11-1930	
6	Jammapura	S.D.O. Davangere Mr. T. Ramiah along with the T.V. Amildar Mr. A. Arunachalam	9-9-30	
7	Uttaregudda in the Harikanive State Forest	Amildar, Hiradenegu Mr. A. Arunachalam	31-12-30	

A3. per. A. 171/30-31

Chitaldrug
07. 22/6/31

Sd/-
for Deputy Commissioner
Chitaldrug district

(6)

Appendix F G–1]

SUBJECT.....

.....

.....

Section Gen.

File No. 101-30

Serial No. 12

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the *193*

Date of issue 11/7/31

Signed by Dwr N. D.

List of enclosures.....

Copied by.....

Examined by.....

No. Pol. 55 C/2.

To

The Secretary to the
Hon'ble the Resident.

Sir,

I am directed to forward herewith the annual report, in duplicate, on the Condition of the F.T.S. States in the Mysore State for the year 1930.

I have etc.,

Chief Secy. to Govt.

CC

Spr. 101-30-13 Pol. 416

[R.O. 106 (a).]

OFFICE OF THE RESIDENT IN MYSORE,

All communications should be addressed to the Secretary to the Resident in Mysore, Bangalore, by designation and not by name.

Bangalore, 17th Septr. 1931.

64

Spr. 1648

No. 6772 Enclos. 6 (11)
382-1931.

290.



A copy of the marginally* noted paper, with enclosures, is forwarded with compliments, to the Chief Secretary to the Government of His Highness the Maharaja of Mysore, with reference to his letter No.Pol.55/Gm. 101-30-12, dated the 11th July, 1931.

*No. 602/8-1(a).47.F.2/D, dated the 18th August, 1931, from the Director, Geodetic Branch, Survey of India, Dehra Dun.

for Secretary to the Resident.

23—10-4-1931—5,000—RPS.

(65

Survey of India.

Geodetic Branch Office,

No.602/8-1(a) Dehra Dun, the 18th August, 1931.
47-F.2/D.

From

The Director, Geodetic Branch.

To

The Secretary to the Resident, Bangalore.

Acknowledges his No.5374/382 of 29th July 1931 giving cover to the Annual Report for the year 1930 on the condition of Stations of the G.T. Survey sent therewith.

I regret that financial stringency prohibits any allotment for repairs during the current year 1931-32. If possible, funds will be allotted during next financial year 1932-33.

2 copies of the form of Annual Return of marginally noted districts for future use,* on the first page of which will be found "Notes on the preparation of the Return" and "Measures necessary for the protection of Stations" which should be strictly adhered to. Attention is also invited to the memorandum printed overleaf.

Forms of annual return for other districts will be sent when printed.

Sd/- x x x

for Director, Geodetic Branch.

1) Kolar.
2) Hassan.
3) Mysore.
4) Bangalore.
5) Shimoga.

This form should always be used in submitting the Annual Return.

"C O P Y"

Superintendent, Resident's Office.

vdv.

PROTECTIVE MEASURES.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the debris is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones a few feet high, over the spot whence the mark-stone has been removed. See also page 1 of the Form of Annual Return for further details, if desired.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs.4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

---

(6)

Fair draft

G.R.S. App. F VI G-2]

SUBJECT.....

.....

.....

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

the 192 .

Date of issue 7/10/31

Signed by Mr. M. Deva Rao

Sec G. M.

File No. 10/-30

Serial No. 14

Proceedings of the Government of His Highness the Maharaja of Mysore.

Read –

the annual report on the condition of G.T.S. stations in the state for the calendar year 1930 received from the deputy commissioners of districts.

Order Thereon No. G.2861-9

..... Recorded.

Govt. regret that owing to financial stringency it is not possible to make any allotment for repairs needed to the G. T. S. stations during the current year 1931-32.

H.M.

General Secretary

P.T.O.

May this be

i Printed?

ii treated as a standing order ?

iii published in the Gazette, English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette, Kannada Part ?

69

PROCEEDINGS OF THE GOVERNMENT OF HIS HIGHNESS THE MAHARAJA OF MYSORE.

Read :—

The annual report on the condition of Great Trignometrical Survey Stations in the State for the calendar year 1930 received from the Deputy Commissioners of Districts.

Order No. G. 2861-9/G. Mis. 101-30-14

Recorded. Dated, Bangalore, 7th October 1931.

Government regret that owing to financial stringency it is not possible to make any allotment for repairs needed to the Great Trignometrical Survey Stations during the current year 1931-32.

By order &c.,
R. Devadas
Chief Secretary to Government.

To

The Deputy Commissioners of Districts.
The Comptroller to Government.

Two drafts.

(-10)

Appendix F G—1]

SUBJECT .....

.....

.....

Section G.M.

File No. 101-30

Serial No. 15

Diary No. of letter replied to .....

General and Revenue Secretariat

( )

the . 193 .

Date of issue 7/10/31

Signed by Mrs. M. Venkata Rao

List of enclosures .....

Copied by .....

Examined by .....

No. G.2870-4/Genl. 2.

To The Dcs of Kolar, Kanara, Mysore, Bangalore and Shimoga.

Sir,

In continuation of G.O. No. G. 2861-9/G.M. 101-30 dated 7th Oct 1931 regarding the annual report on the condition of G.T.S. stations in the state for the calendar year 1930, I am directed to forward herewith a copy of the form of the annual return and to request you to see that this form is used in future, on the first page of which will be found "Notes on the preparation of the Return" and measures necessary for the protection

P.T.O.

Tel. Address:—Depcom,
CHITALDRUG.

In reply, please refer to
No. A3.C.1948/30-31.
Enclosures.

72

OFFICE OF THE DEPUTY COMMISSIONER,
CHITALDRUG DISTRICT.

Dated Chitaldrug, 23rd December 1931.

587.

FROM

M. Seshadri Esquire M.A.,
Deputy Commissioner,
Chitaldrug District.

CHIEF SECRETARY
20 DEC. 1931

TO

N. Madhava Rao Esquire B.A.,B.L.,
Chief Secretary to Government,
B a n g a l o r e.

Sir,

I have the honor to invite kind reference to this office No.A3.C.1948/30-31 dated 27th April 1931 submitting an estimate for Rs 10 for effecting repairs to the Trigonometrical Survey station at Jogimatti, Chitaldrug Taluk and to request the favor of early sanction to the same.

I have the honor to be,
S I R,
Your most obedient servant,

Try: Assistant Commissioner,
For Deputy Commissioner,
Chitaldrug District.

(Absent from station).

(73)

Appendix F G—1]

SUBJECT .....

.....

.....

Section Gen

File No. 401-30

Serial No. 16

Diary No. of letter replied to .....

No. 45477

To the D.C. Chitaldrug.

Sir,

General and Revenue Secretariat

( )

the *193*

With reference to your letter No. A-3-C-1948/30-11 dated 23-12-31 regarding the estimate for Rs 10/- for repairing the Trigonometrical survey station at Jagiriatti, I am directed to invite your kind attention to G.O.No. G 2861-9/G.A. 101-30-14 dated 7-10-1931 observing that owing to financial stringency it is not possible to make any allotment for repairs to G.T.S. stations during the current year and to state that the ~~estimated~~ cost of the estimate may be included, if necessary, in your next annual report.

Date of issue 8.1.32

Signed by Mr. N. Rao

x. W

List of enclosures .....

Copied by .....

Examined by .....

I have etc.

RR 8/1

General Secretary.

WD 71—GBPM—40,000—20-7-31.

RR 31/12.

(74

Letter No. 3269 dated 8th January 1932 from the Deputy Commissioner, Bangalore, to the Chief Secretary to Government.

In continuation of this office letter No.C6-3269/30-31 dated 20-4-1931 re. the repairs to the great Hill Station at Savandurga, I have the honour to forward herewith correspondence ending with Closepet Sub Division Officer's letter No.A2-840 dated 16-12-1931 together with an estimate for Rs.50/- being the cost of repairs prepared by the Executive Engineer, Bangalore, Division for favour of further needful action.

Elections

(75)

Shimoga District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
6. *Paka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last three columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station (Principal)	h. s.	denotes	hill station (secondary)
P. S.	„	Platform Station „	s.		station
S.		Station	t. s.		tower station
T. S.		Tower Station			

Shimoga District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thāna	Names of nearest villages
2978	Ambargudda h. s.	Ambargudda	Maratti	Sagar Taluka	Nagodi, Kolavur, Kodanavalli and Adagalatti
2979	Badankatte h. s.	Tavarekha Thammanagegudda	Barnakatte	Sorab Taluka	Tadanur, Anavatti and Kubatur
2980	Bisale H. S.	Bisalekalla Hill	Hossur	Tirthahalli Taluka	Hurali, Sulibailagudi, Magaravalli and Hossur
2981	Chandragutti H. S.	Chandragutti	Chandragutti	Sorab Taluka	Baragavalli, Igodu and Kodambi
2982	Dindemane H. S.	Dindemanegudda	Karur	Sagar Taluka	Konnammakki
2983	Honnavalli H. S.	Honnavallegudda	Hanavalli	Sorab Taluka	Barur, Indavalli, Kaunur and Hulikatte
2984	Hugadi H. S.	Hugadigudda	Hugadi	Nagar Taluka	Nagarahalli
2985	Kalavarangan h.s.	Kalavarangangudda	Issarapura	Honnali Taluka	Yeraganahalli, Chinkatta and Belagutta
2986	Kalingrayan h.s	Kalingarayan	Halasinavaravu	Channagiri Taluka	Uranti
2987	Kodashadri H.S	Kodashadri parvata	Vallurmane	Sagar Taluka	Vallurmane, Mukkodlu in S. Canara, Kattinahole and Kollur
2988	Koramur H. S.	Koramurgudda	Nijagar Khandaka	Sagar Taluka	Tumbibailalli
2989	Siddeshvar H. S.	Siddeshvaragudda	Surali Balebail	Tirthahalli Taluka	Surali, Balebail, Tirthahalli, Sivarajapura and Ambalihole

Shimoga District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
Platform of rough stones in mud with revetment on the exterior: No pillar or tower. A small excavation in the centre of the platform marks the site of the pillar. The patel was instructed to keep the station clear.		K. Srinivasan Esqr. Asst Commissioner 10-12-30 K Rangappa Esqr. Amildar 10-12-30
Stones that has slipped from the platform were got replaced and the jungle round about the platform cleared at a cost of Rs 3 only	Rs 3/-	M. Narayana Rao, Esqr Amildar 28-12-30
A few stones from the basement on the eastern and northern sides have fallen down. But the platform does not require any immediate repairs		K. G. Mahadevappa Esqr. Special by Amildar 31/12/30
Mound of kutcha stones and earth with holes. No pillar or other structure visible		K. Srinivasan Esqr. Asst Commissioner 8-12-30 K. Rangappa, Esqr. Amildar 8-12-30
The platform and the space around is clear of rank growth; the upper portion of the pedestal is broken at the edges & it requires cement plastering	Rs 4/-	
The Station is quite firm; the debris is slightly in disrepairs owing to last monsoon rains. The pole was unstable and shaky. The debris must be set right and plastered. There is no rank vegetation around. A red flag was got placed on the pole.	Rs 4/-	B. Rachappa Esqr. Amildar.
It is reported that the rank vegetation was got cleared up and trees grown near the platform were cut. The stones that were loose and that had fallen down were set right and fastened.	Rs 4/-	K. Subba Rao Amildar 22-12-1930
One mark stone was taken off the pillars and thrown down the platform. The stone has been placed on the pillar (without mortar) and stones piled over it in the form of a Cone to prevent its removal. Jungle that has grown around was all cleared at a cost of Rs 2/-	Rs 2/-	M. Narayana Rao, Esqr Amildar 28-12-30

Shimoga District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thāna	Names of nearest villages
2990	Timmappanagudda h. s.	Timmappanagudda	Balanayakana-halli	Channagiri Taluka	Basavapatna
2991	Vimaldi h. s.	Udamardi	Kudagalmani	Shimoga Taluka	Settihalli and Heggalatti

Shimoga District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
The station was overgrown with rank grass which was got cleared. The stones of the pillar have been loosened and require to be fixed up with mortar. Otherwise the station is in good condition.	Rs 4/-	N. S. Hiriannaiah, Dsg. Asst Commissioner 31-12-30 T. Raja Rao, Dsg. Amildar 2-1-31
		for Deputy Collector Shimoga

SUPPLEMENT STATEMENT ON THE CONDITION OF THE TRIGONOMETRICAL SURVEY STATIONS IN THE SHIMOGA DISTRICT.

Ledger No.	Survey name of the station	Local name of station.	Village in which the station lies.	Thasil pargana Taluka Thana	Name of the nearest villages	Condition of the station.	Estimated cost of repairs.	Name and Rank of the inspecting Officer and date of inspection.
2978.	Ambargudda H.S.	Ambargudda.	Maratti	Sagar Taluk (Karur hobli)	Nagadi Kodanavalli and Adagalale.	Good.	--	H.Krishnachar Esqr Amildar 19-1-31.
2982.	Dindimane. H.S.	Dindimani gudde.	Karur.	Sagar Taluk (Karur Hobli)	Konnanamakki Uralagallu Kanoor.	It is in the same condition as last year. Requires repairs to the revetment of the platform. Last years estimate not sanctioned.	Rs15/-	H.KrishnacharR Esq Amildar 18-1-31.
2987.	Kodachadri H.S.	Kodachadri Parvata.	Vallur	Sagar Taluk (Karur Hobli)	Valur Kattivahole and Kolur	Good.	- -	H.Krishnachar Esq Amildar 20-1-31.
2988.	Koramur. H.S.	Kormargudda	Gijagar Majre of Khandaka Village.	Sagar Taluk (Talaguppa Hobli)	Benkatavalli Hulikodu Yedajigatemane Dombe.	Quite good.	---	H.Krishnachar Esq Amildar 22-12-30.

D.C. Nimmo

Deputy Commissioner,
Shimoga District.

AS. Per. A4. /30-31

G.R.N

(78 7

Bangalore District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
Paka pyramidal pillars.	6. Cover over with earth and stones as in 4.

NOTE

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station (Principal)	h. s.	denotes	hill station (secondary)
P. S.	,,	Platform Station ,,	s.	,,	station ,,
S.	,,	Station ,,	t. s.	,,	tower station ,,
T. S.	,,	Tower Station ,,			

Bangalore District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
307	Banatimaribetta H. S.	Banantemaribetta	Kotkonhalli	Kankanhalli Taluka	Kotkonhalli
308	Bangalore Base-line N. E. End S.	Kannur	Kannur	Hoskote Taluka	Chota Gubbi
309	Bangalore Base-line N. End s.	Banasavadi	Banasavadi	Bangalore Taluka	Channasandra
310	Bangalore Base-line S. End s.	Harlur	Harlkunte	Bangalore Taluka	Harlur
311	Bangalore Base-line S. W. End S.	Uyalkaval	Uyalkaval	Bangalore Taluka	On the north of the Bangalore Cantonment
312	Bannergatta H. S.	Bannergatta	Bannergatta	Anekal Taluka	Sampigehalli and Bairappanahalli
313	Basavangudda h. s.	Kodugpalli	Kodugpalli	Bangalore Taluka	Kodugpalli
314	Doddagunta s.	Doddagunta	Doddagunta	Civil and Military Station of Bangalore	Jibanahalli
315	Geddahalli h. s.	Gadalhalli	Gadalahalli	Bangalore Taluka	Gadalahalli
316	Gubbi s.	Kalsanhalli	Kalsanhalli	Hoskote Taluka	Chota Gubbi
317	Halasurbetta H. S.	Alasur Hill	Betta Alasur	Devanhalli Taluka	Jodi Kadagunahalli, Bilimaranhalli and Sinappanahalli
318	Hennur s.	Hennur	Hennur	Bangalore Taluka	Hennur

Bangalore District

Condition of station	Name & rank of inspecting officer & date of inspection	Estimated cost of repairs Rs.	As.	P.
The Trigonometrical plane is lying in the Taluk Office at Kankanhalli. It is learnt that as the plane had been removed from its place it was brought and kept in the Taluk Office for being refixed after Consulting the Survey of India Department in regard to the exact point.	Mr. V. Dwaraka Nath, B.A.B.L. Sub Division Officer Close pet.			
Reported to be in good Condition	Mr. Abdul Hakk B.A. Sub Division Officer			
Is in good Condition.	Mr. T. Abdul Khader B.A. Sub Division officer 20.7.30.			
Is in good Condition	D.O. 19.7.30.			
D.O.	D.O. 9.11.30.			
D.O.	D.O. 6.7.30.			
Is in good Condition	Mr. T. Abdul Khader B.A. Sub Division officer 6.7.30.			
—	—			
Is in good Condition	Mr. T. Abdul Khader B.A. Sub Division officer 12.7.30.			
D.O.	D.O. 9.10.30.			
Reported to be in good Condition	Mr. M. Abdul Hakk B.A. Sub Division officer			
Is in good Condition	Mr. T. Abdul Khader B.A. Sub Division Officer 9.11.30.			

Bangalore District

Index No.	Survey Name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
319	Kalkote h. s.	Kulkota	Kulkota	Dodballapur Taluka	Varavani and Manchenahalli
320	Koppabetta H. S.	Koppabetta	Kotakuppa	Kankanhalli Taluka	Arakeppa and Dodkuppa
321	Machalbetta s.	Lingarajpura	Between Lingarajpura & Dodkunte	Bangalore Taluka	Lingarajpura
322	Makalidurga H. S.	Makalbetta	Makli	Dodballapur Taluka	Somenahalli, Mandi, Gundangiri and Kumbalahalli
323	Mandur H. S.	Dodgutta	Mandur	Hoskote Taluka	Gundur and Baiyappanahalli
324	Nandigudi H. S.	Nandigudi	Nandigudi	Hoskote Taluka	Banahalli
325	Sampigehalli t. s.	Sampgehalli	Sampgehalli	Bangalore Taluka	Sriramapuram and Sampgehalli
326	Savandurga H.S.	Savandurga	Karisavandurga near Basavana Temple	Magadi Taluka	Nilapatna Kalyana Devara Matt and Nargikanpalya
327	Tirthapalli H. S.	Tirthalli	Tirthalli	Hoskote Taluka	Jodi Tagri Hoshalli
328	Turukungutta H. S.	Turakungutta	Doddanskundi	Bangalore Taluka	Sitaramappanapalya

Bangalore District

Condition of station	Name of rank & initials of inspecting officer & date of inspection	Estimated cost of repairs Rs.	As.	P.
Reported to be in good Condition	Mr. M. Abdul Hakh. BA. Sub Division Officer			
Is fairly fixed	Mr. V. Dwarakanath B.A. B.L. Sub Division Officer Closepet.			
Is in good Condition	Mr. T. Abdul Khader. B.A. Sub Division Officer 20. 7. 30.			
Reported to be in good Condition	Mr. M. Abdul Hakh BA Sub Division Officer			
In good Condition	Mr. M. Abdul Hakh BA Sub Division Officer 11. 11. 30.			
Pedestal has been Completely demolished and the stone slab was found at a distance. Special report was submitted to the Dy Commr to get the estimate sanctioned.	Mr. M. Abdul Hakh. B.A. Sub Division Officer 26. 9. 30.	The estimate has been sanctioned and necessary actions being undertaken. according to Govt order 2465-92 P.W. 68-29-27 Dt 13. 12. 30.		
Is in good Condition	Mr. T. Abdul Khader BA Sub Division Officer 13. 9. 30			
Is reported to be Satisfactory	Mr. V. Dwarakanath BA B.L Sub Division Officer Closepet.			
In good Condition	Mr. M. Abdul Hakh BA Sub Division Officer 11. 11. 30			
Is in good Condition	Mr. T. Abdul Khader BA Sub Division Officer 18. 9. 30.			

for Chief Engr
for Deputy Commr
Bangalore Dt.

15/1/31
DAK.

16/1

Kolar District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
6. *Paka* pyramidal pillars.	6. Cover over with earth and stones as in **4.**

NOTE

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last three columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station (Principal)	h. s.	denotes	hill station (secondary)
P. S.	,,	Platform Station ,,	s.	,,	station ,,
S.	,,	Station ,,	t. s.	,,	tower station ,,
T. S.	,,	Tower Station ,,			

Kolar District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
1939	Ambajidurga H. S.	Ambajidurga	Upparpet	Sidlagatta now Chintamani Taluka	Waddarpalli, Kavalgadurga, Chorapalli and Konapalli
1940	Bandapalle H. S.	Bandapallibeta	Bandapalli	Mulbagal Taluka	Reddipalli, Edahalli, Honnasettihalli, Varukunte and Mittur
1941	Bhupatamma H. S.	Bhupattammabetta	Ulerhalli	Malur Taluka	Virakapura, Somasandra and Timmanayakanahalli
1942	Chikkapalli h. s	Chikkapalli	Chikkapalli	Sidlagatta now Chintamani Taluka	Yerranagenahalli, Mittamari and Sadali
1943	Itikaldurga h. s.	Devekunte	Devekunte	Bagapalli Taluka	Marganhunte and Thangedkunte in British Territory
1944	Kolar H S.	Paparaganahallidurga belonging to the Kolar Range	Paparaganahalli	Kolar Taluka	There are no villages in the vicinity
1945	Konkontlu h. s.	Siddarmallibetta	Bodimpalli	Sidlagatta now Chintamani Taluka	Munganhalli, Bettalahalli, Koddigalla and Iragampalli
1946	Kurudamale H S.	Kurudamallebetta	Kurudamalle	Mulbagal Taluka	Madagatta, Siddagatta, Kachabandihalli and Arehalli
1947	Nundydroog h. s.	Nandidroog	Sultánpet	Chikballapur Taluka	Nandi, Kadavati and Viranahalli
1948	Rahmanghar h. s.	Rymandurga	Hosapet near Kaivara	Sidlagatta now Chintamani Taluka	Kaivara
1949	Yerrakonda H. S.	Byatarayanahallibetta	Byatarayanahalli	Betmangala now Bowringpet Taluka	Madamangala, Doddakallahalli, Kempapura, Chambarsanahalli and Lakkinayakanahalli

Kolar District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
In good condition. Requires no repairs	-	J. V. A. Isvaran Esq. B.A. Asst: Comr: Chickballapur Sub Divn: on 18.9.30
In good condition except the stone revetment requiring slight repairs	-	S. N. Appanna Ayengar Esq. B.A.B.L. Asst: Comr: Kolar Sub Divn: on 25.12.30
In good condition except the platform which requires little plastering.	Estimate has been called for.	Inspected by the Amildar of Malur Taluk on 31-12-30
In good order		J. V. A Isvaran Esq. B.A. Asst: Comr: Chickballapur Sub Divn: on 16.12.30
In good condition		do on 7-12-30
In good condition.		The Amildar of Kolar Taluk on 30.12.30
In good order		J. V. A Isvaran Esq. B.A. Asst: Comr: Chickballapur Sub Divn: 18.9.30
In good condition		S. N. Appanna Ayengar Esq. B.A.B.L. Asst: Comr: Kolar Sub Divn: on 28.12.30
do		J. V. A Isvaran Esq. B.A. Asst: Comr: Chickballapur Sub Divn: on 22.12.30
Jungle growth cleared and now in good Condition.		do on 21-12-30
In good condition except the platform requiring plastering.	Estimate has been called for	S. N. Appanna Ayengar Esq. B.A.B.L. Asst: Comr: Kolar Sub Divn: on 31-12-30
Forwarded, with Compliments to the Chief Secretary to Govt: of Mysore, Bangalore.		

For Deputy Commissioner
Kolar Dist.

(80

Hassan District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
6. *Paka* pyramidal pillars.	6. Cover over with earth and stones as in 4.

NOTE

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last three columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station	(Principal)	h. s.	denotes	hill station (secondary)
P. S.	,,	Platform Station	,,	s.	,,	station ,,
S.	,,	Station	,,	t. s.	,,	tower station ,,
T. S.	,,	Tower Station	,,			

Hassan District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
1454	Desani h. s.	Desaingudda (Dodchingiuabetta)	Desani	Arsikere Taluka	Kurudahalli, Handrahalli and Kallyadi
1455	Kittavar H. S.	Kittavaradagudda	Anughatta	Belur Taluka	Salavara
1456	Mallappanabetta h. s.	Mallesvarabetta	Bijemarnahalli	Hassan Taluka	Mavanur
1457	Nughallibetta H.S.	Joginathgudda	Nughalli	Chennaroyapatna Taluka	Nughalli
1458	Satanhalli H. S.	Satenahallibetta	Satenahalli	Hole-Narsipur Taluka	Satenahalli

Hassan District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
	Rs.	
Quite good.	—	M. Ramaswamiah Esq M.A. B.L.B. Amildar Arsikere 29-12-30.
The Station is in good condition. The masonary work which has been repaired last December is in-tact	—	B. N. Sitaramiah Esq M.A Amildar Belur Taluk 24-12-1930.
The Station is at the top of the hill near the Malledevaru temple. It is a low platform constructed in stone in mortar. It is in good condition	—	C. Gopalachar Esq B.A. Senior Assistant Comr Hassan Sub division 29-12-1930.
This consists of a square pedestal of kaccha stone and earth with a wooden pole stuck up in the centre. This is in good condition		—do— 25-9-1930.
It consists of a Mound of rough stones and is in good condition. No repairs needed.		—do— 3-12-1930.
5/1/1931.	Deputy Comr & Ex-Officio Hassan District.	

Mysore District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
The Station is in good condition.		Mr.B.Lakshmana Rao, Amildar, Mandya Taluk 30-12-1930.
Station is good, but the dry rough stone platform has gone in one or two places. A little mortar plastering to the main pedestal is necessary. The Patel of Chikkakoppal and Revenue Inspector have been asked to complete the repairs and submit a bill so that it may not go worse.	Rs 2/-	Mr.Md.Ismail Sheriff, Revenue S.D.O., Mysore Sub Division. 29-10-1930.
Both the platform and the tower are in good condition. The chunnam patti running through the border of the tower at the bottom requires slight repairs. Government sanctioned repairs to the ~~extent of Rs 2/- which will be got executed.~~	Rs 2/-	Mr.J.Appaji Gowda, Asst.Commissioner I/C French Rocks Sub Division 16-11-1930 ~~Mr.B.Sreenivasa~~ Murthi, Amildar, Nagamangala on 16-11-1930.
The platform and the pillar are in good condition.		Mr.J.Appaji Gowda, Asst.Commissioner in charge of French Rocks Sub Division ~~4-12-1930.~~ Mr.H.N.Pallegar, Amildar, Krishnarajpet on 4-12-1930.

Dated 15th January 1931.

For Deputy Commissioner,
Mysore District.

Mysore District

Ledger No.	Name of the station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of neighbouring villages
2438	Adhibetta H.S.	Adhibetta	Hatnabettahalli	Mandya Taluka	Hatnabetta
2439	Adhurbetta H.S.	Adhurbetta	Halliur Bedarhalli	Yedatore Taluka	Kuppe Fi ka ur Yadatore
~~2440~~	~~Bettadpur h.s.~~	~~Bettadapuradabetta~~	~~Bettadapur~~	~~Hunsur Taluka~~	Bettadapura
2441	Haltibetta H.S.	Halattibetta	Kachenahalli and Halatti	Nagamangala Taluka	Kenchenahalli and Halatti
~~2442~~	~~Kundur h.s.~~	~~Kundurbetta~~	~~Kundur~~	~~Malavalli Taluka~~	Kundur
~~2443~~	~~Mysore No. 3 h.s.~~	~~Chamundibetta~~	Chamundibetta, Kudanhalli	~~Mysore Taluka~~	Chamundibetta
2444	Narayandurga H.S.	Narayanagiribetta	Sindaghatta	Krishnarajpet Taluka	Kodiballi, Sindaghatta, Rayasamudra and Harohalli

(81)

Kadur District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
6. *Paka* pyramidal pillars.	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last three columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station (Principal)	h. s.	denotes	hill station (secondary)
P. S.	„	Platform Station „	s.	„	station „
S.	„	Station „	t. s.	„	tower station „
T. S.	„	Tower Station „			

Kadur District

Ledger No.	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
1770	Anur H.S.	Rangaswamigiri	Hanucharvalle	Chikmagalur Taluka	Mavinguni and Busgode
1771	Ballalrayandurga h.s.	Balalarainadurga	Dugadahalli	Mudgere Taluka	Balige and Dugadahalli of Meibangadi Magani
1772	Hebbe H.S.	Hebbe	Hebbe	Chikmagalur Taluka	Koragalli and Hebbe
1773	Hiregudda H.S.	Hiregudda	Hiregudda	Koppa Taluka	Yelemalli and Solebile, Baggunji Magani
1774	Valkunji H.S.	Walkunji	Vurvani (Mudba)	Koppa Taluka	Kerekutta and Vurvani

For the year 1930

Kadur District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
Inspected on 17-12-30 Good condition	Rs. Nil	R. Srinivasa Rao Esqr. B.A., Amildar Chikmagalur on 17-12-30
Inspected on 14-11-30. The Amildar reports that the plat form requires to be repaired and a pyramidal pile of earth and stones constructed, and that a sum of Rs 4/- is required for this purposes. An estimate has been called for.	*4/-	G. Ramachendra Rao Esqr. B.A., Amildar Kadur 14-11-30
Inspected on 29.12.30. Good condition.	Nil	R. Srinivasa Rao Esqr. B.A., Amildar Chikmagalur 29-12-30
Inspected on 29-12-30 Good condition.	Nil	S. Narasinga Rao Esqr. Amildar Koppa
Inspected on 23-12-30 Good condition	Nil	Mr. B. Narasimha murthi Revenue Inspector
H. Nagaraja for Deputy Commissioner Kadur District.		
*D.C Kadur's Letter No A.7-1846-30/48 dated 26-2-1931.		

Tumkur District

Condition of station	Estimated cost of repairs	Name and Rank of Inspecting Officer and date of Inspection
Good.		Mr.C.Lakshmana Rao,BaA.,B.L., Gubbi Sub Dn. Officer 17.7.30.
Good		Mr.M. Puttaswami Amildar Madhugiri Taluk. 30-12-1930.
Reports that it was recently repaired and is in good condition. Inspected by Mr.B. Lakshmana Rao, B.A.B.L. Sub Division officer, Gubbi, on 27-12-1930 and is reported to be in good condition.		Mr.M. Venkatagiri Setty,B.A. Amildar,Tuhuvekere on 18-12-30
Good. Inspected by Mr. A.L. Puttaiya, Amildar,Tumkur on 21-1-1930 and 29-4-30. Inspected by Mr. K. Ramaswamy, Taluk Sheristedar who was in charge of the Taluk on 25-12-1930. Inspected by the Sub Dn. Officer Tumkur Sub Dn: on 25-12-1930.		Mr.G.B. Pehlikar Deputy Commissioner,Tumkur District. 21-1-1930.
Good.		Mr.M. Puttaswami B.A.,Amildar Madhugiri 29-12-1930.
Good		Mr.B.P. Saraf, B.A., LL.B., Amildar,Kunigal 28-12-30.
Reports that the pyramid is damaged on the sides and also on the top and that it is to be repaired and whitewashed	Rs. 2/-	Mr.P.K.Doraswami Iyengar,B.A., Amildar,Pavagada 24-12-1930.
Good		A.L. Puttaiya Amildar,Tumkur 30-12-1930.
Good		Mr.B.P. Saraf B.A.,LL.B., Amildar,Kunigal 25-12-1930.
Reports that the pedestal of the bench mark is damaged and requires repairs.	2/-	Mr.L.Muniswami B.A., Amildar, Koratagere 13-11-1930.

For Deputy Commissioner,

(8

4	5	6
Pargana, Taluka, Thana	Names of nearest villages	Condition of station and estimated cost of repairs
Vasagada Taluka	Vasagada Rampura Borumalidevi Kelamamadevi Valiyamadevi Veerapamadevi	The station is in a good state of repair except that in the north ~~the~~ layer of bricks ~~are~~ 2 and bricks have fallen off. They require to be replaced with mortar. It may cost about 80 Rs.

7E.2701/30

Submitted to the Deputy Commissioner, Surat.

9-1-31
AG

Asst. Commissioner
Vasagada Sub-Division

1	2	3	
Survey name of station	Local name of station	Village in which the station lies	Tahsi
Pasayada Trigonometrical Survey Station	Pasayada Trigonometrical Survey Station	Pasayada	P

Date of erection
31st December 1930

Tumkur District

Annual Return shewing the condition of the Pillars and Towers or Platforms marking the Principal and Secondary Stations of the Trigonometrical Survey.

Measures necessary for the Protection of Stations.

Description of Station.	*Protective Measures*
1. Hollow Towers of *paka* masonry.	1. Stop all cracks; close the trap door; block up the windows and the doors in the basement; and should the roof-fall in, shape the *débris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones, in the form of a pyramid.
2. Solid Towers of *kacha* masonry, with a central solid *paka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *kacha* masonry, with a central perforated *paka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *kacha* materials with a central solid *paka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Paka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodging near the base of the pillar.
6. *Paka* pyramidal pillars.	6. Cover over with earth and stones as in 4.

NOTE

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when therefore a pillar has entirely fallen down, it will suffice if the *débris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high, over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts &c. any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last three columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent of the Trigonometrical Survey, Dehra Dún.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes	Hill Station (Principal)	h. s.	denotes	hill station (secondary)
P. S.	„	Platform Station „	s.	„	station „
S.	„	Station „	t. s.	„	tower station „
T. S.	„	Tower Station „			

Tumkur District

No.	Survey number of station	Name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Name of village
3408	Bommanhalli h.s.	Bommanahallibetta	Bommanahalli	Tiptur Taluka	Gollarahatti, Gollara Bommanahalli and Hi
3407	Byal h.s.	Baliappibetta	Byalya	Maddagiri Taluka	Settihalli, Kotta and Nega
3405	Chaudanhalli S.	Krishnapura	Between Chandamhalli and Krishnapura	Tiptur Taluka	Chandamhalli, Krishnapura, Bommanahalli, Tiptur and Ke
3409	Devarayadurga h.s.	Devarayadurgbetta	Devarayadurga	Tumkur Taluka	Antharasanahalli, Tumkur, Devarayadurga and Durgada
3410	Dodnirmanga H.S.	Dodnirmanga	Kavanadala	Maddagiri Taluka	Timmalapura, Kavanadala
3411	Hemagiri H.S.	A hill near Rungaswamibetta and Hutridurgabetta	Huliyurdurga	Kunigal Taluka	Huliyurdurga, Kyatsandra, Hutridurga, Kyatsandra and Vaderahalli
3412	Pavagada H.S.	Sultanbateri	Pavagada	Pavagada Taluka	Pavagada and Karigatta
3413	Ramadevarabetta H.S.	Ramadevarbetta	Basavapatna	Tumkur Taluka	Basavapatna, Kariyappanapalya, Boorugamakanapalya and Siddagangemutt
3414	Rangaswamibetta H.S.	On the west of the Hutridurga hill and Kunigal	Kothgiri and Gunagra	Kunigal Taluka	Kunigal, Nagamangala, Kalagatlapalya and Bommenagiri
3415	Sitakal h.s.	Ramadevarbetta	Sitakallu	~~Tumkur~~ Konatapeta Taluka	Sitakallu, Betta Sitakallu, Kalenahalli and Gangenahalli

TUMKUR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

DESCRIPTION OF STATION.	PROTECTIVE MEASURES.
1. Hollow Towers of *Pakka* masonry . .	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

TUMKUR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
3406	Bommanahalli, H. S.	Bommanahalli-betta.	Bommanahalli	Tiptur Taluka	Godabanahal Guladahalli, Bommanahalli and Hoshalli
3407	Byal, H. S. ...	Bailappibetta...	Byalya ...	Maddagiri Taluka.	Settihalli Puttanahalli and Soganahalli.
3408	Chowdanhalli, S	Krishnapura...	Between Chandamhalli and Krishnapura.	Tiptur Taluka	Chandamhalli Krisnapura Doddenahalli and Turuvekere.
3409	Devarayadurga, H. S.	Devarayadurga-betta.	Devarayadurga	Tumkur Taluka	Aunapanahalli Thimmanayakanahalli and Durgadahalli.
3410	Dodnimanga, H. S.	Dodnimanga...	Kavanadala ...	Maddagiri Taluka.	Timmapura and Kavanadala.
3411	Hulimagiri, H. S.	A hill near Rangaswamibetta and Hutridurgabetta.	Huliyurdurga...	Kunigal Taluka	Huliyurdurga Ujini, Hettipur and Viradarayanapalya
3412	Pavagada, H.S	Sirambateri ...	Pavagada ...	Pavagada Taluka.	Pavagada and Rangapura
3413	Ramadevarabetta, H. S	Ramadevarbetta	Basavanatna...	Tumkur Taluka	Basavapatna Karikallu Bommenahadapalya and Siddaramatti
3414	Rangaswamibetta, H. S	One mile west of the Hutridurga hill and Kunigal	Kothgiri and Gunagra.	Kunigal Taluka	Kunigal N. Hanumavarapura Kalagatta and Bommegowdanadoddi
3415	Sitakallu, H. S.	Ramadevarbetta	Sitakallu ..	Tumkur Taluka	Sitakallu, Betta Sitekallu Kalenahalli and Gollarahalli

TUMKUR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

Description of Station.	Protective Measures.
1. Hollow Towers of *Pakka* masonry . .	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S.	denotes Hill Station (Principal)	h. s.	denotes hill station (secondary.)
P. S.	„ Platform Station „	s.	„ station „
S.	„ Station „	t. s.	„ tower station „
T. S.	„ Tower Station „		

TUMKUR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
3406	Bommanahalli, H. S.	Bommanahal'i-betta	Bommanahalli	Tiptur Taluka	Godabonahal, Guladahalli, Bommanahalli and Hoshalli
3407	Byal, H. S. ...	Ballippibetta ...	Byalya ...	Maddagiri Taluka.	Settiha... Puttana... and Sogan. halli.
3408	Chowdanhalli, S.	Krishnapura ...	Between Chandamhalli and Krishnapura.	Tiptur Taluka	Chandam... Krishnapura, Doddenahal and Turuv kere.
3409	Devarayadurga, H. S.	Devarayadurga-betta.	Devarayadurga	Tumkur Taluka	Aunapanahalli, Thimmanayakanahalli and Durgadehalli
3410	Dodnirmanga, H. S.	Dodnirmanga ...	Kavanadala ...	Maddagiri Taluka.	Timmapura and Kavanadala.
3411	Hemagiri, H.S.	A hill near Rangaswamibetta and Hutridurgabetta.	Huliyurdurga ...	Kunigal Taluka	Huliyurdurga, Upper Hottapura and Nandarajanapalya
3412	Pavagada, H.S.	Sultanbatteri ...	Pavagada ...	Pavagada Taluka.	Pavagada and Rangenna
3413	Ratnadevarabetta, H. S.	Ratnadevarbetta	Basavapatna ...	Tumkur Taluka	Basavapatna, Kambadahalli, Bommagondanahalli, Siddasirgeri
3414	Rangaswamibetta, H. S.	On the west of the Hutridurga hill and Kunigal	Kothgirikaval and Gunagan...	Kunigal Taluka	Kunigal, Nidasale, Kadasogi, Bommanahalli
3415	Sitakallu ...	Ratnadevarbetta	Sitakallu ...	Tumkur Taluka	Sitakallubetta, Sirsi, Kallenahalli and Gangenahalli

GEOGRAPHICAL SURVEY

TUMKUR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

Description of Station.	Protective Measures.
1. Hollow Towers of *Pakka* masonry . .	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

TUMKUR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
3406	Bommanahalli, H. S.	Bommanahalli-betta	Bommanahalli	Tiptur Taluka	Godabonahalli, Guladahalli, Bommanahalli and Hoshalli.
3407	Byalya, H. S. ...	Balleppabetta...	Byalya ...	Maddagiri Taluka.	Settihalli, Puttanahalli and Soganahalli.
3408	Chowdambalh, S.	Krishnapura...	Between Chandamhalli and Krishnapura.	Tiptur Taluka	Chandamhalli, Krishnapura, Doddenahalli and Turuvekere.
3409	Devarayadurga, H. S.	Devarayadurga-betta	Devarayadurga	Tumkur Taluka	Aunapanahalli, Thimmanayakanahalli and Durgadahalli.
3410	Doddimanga, H. S.	Doddimanga ..	Kavanadala ...	Maddagiri Taluka.	Timmalapura and Kavanadala.
3411	Huliyurdurga, H. S.	A hill near Ranganswamibetta and Huttidurgabetta	Huliyurdurga.	Kunigal Taluka	Huliyurdurga, Ujini, Hettapur and Varadarajanapalya.
3412	Pavagada, H. S.	Subbarayanabetta ...	Pavagada ...	Pavagada Taluka.	Pavagada and Rangapura.
3413	Ramadevarabetta, H. S.	Basavanabetta	Basavapatna...	Tumkur Taluka	Basavapatna, Karikallayya, Boorugamaddapalya and Siddagangematt.
3414	Rangaswamibetta, H. S.	On the west of the Huttidurga and Kun...	Kothgiri and Gunagra.	Kunigal Taluka	Kunigal, Narasimhapur, Kalagenapalya and Bommadagiri.
3415	Sitakallu, H. S.	Hanumanabetta	Sitakallu ..	Tumkur Taluka	Sitakallu, Betta Sitakallu, Kalenahalli and Guddenalli.

TUMKUR DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and Rank of Inspecting Officer and date of Inspection.
Good				Mr. C. Lakshmana Rao, B.A., B.L Gubbi Sub Dn. Officer, 17-7-30.
Good				Mr. M. Puttaswami Amildar Madhugiri Tk. 30-12-1930.
Reports that it was recently repaired and is in good condition. Inspected by Mr. B. Lakshmana Rao, B.A., B.L., Sub Dn. Officer, Gubbi, on 27-12-30 and is reported to be g in good condition.		a		Mr. M. Venkatagiri Setty, B.A., Amildar Turuvekere on 18-12-30.
Good. Inspected by Mr. A.L. Puttaiye, Amildar, Tumkur on 21-1-1930 and 29-4-30. Inspected by Mr. Ramaswamy, Taluk Sheristedar who was in charge of the Taluk on 25-12-1930. Inspected by the				Mr. G. B. Heblikar Deputy Commissioner Tumkur District 21-1-1930.
Good				

TUMKUR DISTRICT.

Condition of station	Estimated cost of repairs			Name and Rank of Inspecting Officer and date of Inspection.
	Rs.	a.	p.	
Good				Mr. C. Lakshmana Rao, B.A., B.L Gubbi Sub Dn. Officer, 17-7-30.
Good				Mr. M. Puttaswami Amildar Madhugiri Tk. 30-12-1930.
Reports that it was recently repaired and is in good condition. Inspected by Mr. B. Lakshmana Rao, B.A., B.L., Sub Dn. Officer, Gubbi, on 27-12-30 and is reported to be g in good condition.		a		Mr. M. Venkatagiri Setty, B.A., Amildar Turuvekere on 18-12-30.
Good. Inspected by Mr. A.L. Puttaiya, Amildar, Tumkur on 21-1-1930 and 29-4-30. Inspected by Mr. Ramaswamy, Taluk Sheristedar who was in charge of the Taluk a 25-12-1930. Inspected by the				Mr. G. B. Heblikar Deputy Commissioner Tumkur District 21-1-1930.
Good				

TUMKUR DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and Rank of Inspecting Officer and date of Inspection.
Good				Mr. C. Lakshmana Rao, B.A., B.L Gubbi Sub Dn. Officer, 17-7-30.
Good				Mr. M. Puttaswami Amildar Madhugiri Tk. 30-12-1930.
Reports that it was recently repaired and is in good condition. Inspected by Mr. B. Lakshmana Rao, B.A., B.L., Sub Dn. Officer, Gubbi, on 27-12-30 and is reported to be g in good condition.		a		Mr. M. Venkatagiri Setty, B.A., Amildar Turuvekere on 18-12-30.
Good. Inspected by Mr. A.L. Puttaiya, Amildar, Tumkur on 21-1-1930 and 29-4-30. Inspected by Mr. Ramaswamy, Taluk Sheristedar who was in charge of the Taluk a 25-12-1930. Inspected by the				Mr. G. B. Heblikar Deputy Commissioner Tumkur District 21-1-1930.
Good				

HASSAN DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

DESCRIPTION OF STATION.	PROTECTIVE MEASURES.
1. Hollow Towers of *Pakka* masonry ..	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

HASSAN DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana Taluka, Thana	Names of villages
1454	Desani, H. S.	Desaingudda, (Dodchinginabetta).	Desani	Arsikere Taluka	Kurubahalli, Handrahalli and Kallyadi
1455	Kittavar, H. S.	Kittavaradagudda	Anughatta ...	Belur Taluka...	Sa...
1456	Mallappanabetta, H. S.	Malleswarabetta	Bijemarnahalli	Hassan Taluka	Ma...
1457	Nughallibetta, H. S.	Joginathgudda	Nughalli	Channarayapatna Taluka	N...
1458	Satanhalli, H. S.	Satenahallibetta	Satenahalli	Hole-Narsipur Taluka.	S...

HASSAN DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and R of Inspecting Officer and dated of Inspection.
Quite good.				M. Ramaswamiah, Esq., M.A., LL. Amildar, Arsikere. 29-12-30.
The station is in good condition. The masonary work which has been repaired last December is in tact.				B. N. Sitaramiah Esq., M.A., Amildar, Bolur Taluk. 24-12-1930.
The station is at the top of the hill near the Malledevara temple. It is a low platform constructed of stone and mortar. It is in good condition.				C. Gopalachar, Esq., B.A., Senior Assista Commissioner, Hassan Sub Division. 22-10-1930.
This consists of a square pedestal of kaccena stone and earth with a wooden pole stuck up in the centre. This is in good condition.				- do - 23-12-1930.
It consists of a mound of rough stones and is in good condition. No repairs needed.				- do - 3-12-1930.

TUMKUR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

DESCRIPTION OF STATION.	PROTECTIVE MEASURES.
1. Hollow Towers of *Pakka* masonry	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

TUMKUR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
3406	Bommanahalli H. S.	Bommanahalli-betta.	Bommanahalli	Tiptur Taluka	Gollacanahalli, Gollacanalli, Bommanahalli and Hosahalli
3407	Byal, H. S. ...	Ballippibetta...	Byalya ...	Maddagiri Taluka.	Settihalli, Puttanahalli and Sogenahalli
3408	Chowlarahalli, S	Krishnapura...	Between Chandamballi and Krishnapura.	Tiptur Taluka	Chandamballi, Krishnapura, Doddenahalli and Tiptur kere
3409	Devarayadurga, H. S.	Devarayadurga-betta.	Devarayadurga	Tumkur Taluka	Aunapanahalli, Thimmanavakanahalli and Dasihalli
3410	Dodnimmanga, H. S.	Dodnimmanga...	Kavanadala ...	Maddagiri Taluka.	Timmapura and Kavanadala.
3411	Huliyurdurga, H. S.	Near Rangaswami-betta and Hutridurga-betta.	Huliyurdurga	Kunigal Taluka	Huliyurdurga, Upparapura and Virupadarajanapalya.
3412	Pavagada, H.S.	Sitambatee ...	Pavagada ...	Pavagada Taluka.	Pavagada and Rangapura.
3413	Ramadevarabetta, H. S.	Ramadevarbetta.	Basavapatna...	Tumkur Taluka	Basavapatna, Kariyappanapalya, Boorugamakalapalya and Siddarangamatti.
3414	Rangaswamibetta, H. S.	On the west of the Hutridurga and Kunigal.	Kothgiri and Guragur.	Kunigal Taluka	Kunigal, Nagamangala, Kadasogenahalli and Bommagatta.
3415	Sitakallu, H. S.	Kalenahalli-betta	Sitakallu ...	Tumkur Taluka	Sitakallu, Near Sitakallu, Kalenahalli and Gudihalli.

TUMKUR DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and Rank of Inspecting Officer and date of Inspection.
Good.				Mr. C. Lakshmana Rao, B.A.BL., Gubbi Sub Dn Officer. 17.7.30
Good.				Mr. M. Puttaswami Amildar Madhugiri Taluk. 30-12-1930.
Reports that it was recently repaired and is in good condition. Inspected by Mr. B. Lakshmana Rao, B.A., B.L. Sub Division Officer, Gubbi, on 27-12-1930 and is reported to be in good condiion.				Mr. M. Venkata giri Setty, B. Amildar, Turuvekere on 18-12-30.
Good. Inspected by Mr. A.L. Puttaiya, Amildar, Tumkur on 21-1-1930 and 29-4-30. Inspected by Mr. K. Ramaswamy Taluk Sheristedar ~~Chaa~~ who was in charge of the Taluk on 25-12-1930. Inspected by the sub division officer, Tumkur sub division on 25-12-1930.				Mr. G. B. Heblikar, Deputy Commissionor, Tumkur District 21-1-1930.
Good.				Mr. M. Puttaswami B.A., Amildar Madhugiri 29-12-30.
Good.				Mr. B. P. Saraf, B.A., LLB, Amildar, Kunigal 28-12-30.
Reports that the pyramid is damaged on the sides and also on the top and that it is to be repaired and whitewashed. The topmost layer of bricks 2 & 3 bricks have fallen off and require to be replaced. Inspected by Mr. R. Thammaji Rao, Sub division officer on 31-12-30.	2/-	-		Mr. P. K. Doraswami Iyengar, B.A., Amildar, Pavagada. 24-12-30
Good.				Mr. A. L. Puttaiya Amildar, Tumkur 30-12-1930.
Good.				Mr. B. P. Saraf B.A., LL.B., Amildar, Kunigal 25-12-1930.
Reports that the pedestal of the bench mark is damaged and requires repairs.	2/-			Mr. L. Muniswami B.A. Amildar Korategere 13-11-1930.

KADUR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

Description of Station.	Protective Measures.
1. Hollow Towers of *Pakka* masonry ..	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

KADUR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana Taluka, Thana	Names of nearest villages
1770	Anur. H. S ...	Rangaswamigiri	Hanucharvalle	Chikmagalur Taluka.	Mavinguni and Busgode.
1771	Ballalarayan durga, h. s.	Ballalaraimadurga	Dugadahalli ..	Mudgere Taluka	Balige and Dugudahalli of Melbangadi Magani.
1772	Hebbe H. S...	Hebbe ..	Hebbe ..	Chikmagalur Taluka.	Koragalli and Hebbe.
1773	Hiregudda. H. S.	Hiregudda ..	Hiregudda ..	Koppa Taluka	Yelampalla and Sollebile Bangunji Magani
1774	Valkunji. H. S.	Walkunji ..	Vurvani (Mudba)	Koppa Taluka	Kerekutta and Vurvani

KADUR DISTRICT.

Condition of station	Estimated cost of repairs			Name and Rank of Inspecting Officer and date of Inspection.
	Rs.	a.	p.	
~~Inspected on 17-12-30~~ - Good condition.				R. Srinivasa Rao, Esq., BA Amildar, Chikmagalur on 17-12-30.
Inspected on 14-11-30. The Amildar reports that the platform requires to be repaired and a pyramidal pile of earth and stones constructed and that a sum of Rs.4/- is required for this purposes. ~~An estimate has been called for~~	4/-	-		G. Ramachandra Rao, Esq., B.A Amildar Chikmagalur Mudigere 14-11-30
Inspected on 29-12-30 - Good condition.				R. Srinivasa Rao, Esq,, B.A., Amildar Chikmagalur 29-12-30
Inspected on 29-12-30 - Good condition.				S. Narasinga Rao, Esq,, Amildar, Koppa. 29-12-30.
Inspected on 23-12-30 - Good Condition.				Mr. B. Narasimha murthi, Revenue Inspector. 23-12-1930.

(9)

SHIMOGA DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

DESCRIPTION OF STATION.	PROTECTIVE MEASURES.
1. Hollow Towers of *Pakka* masonry ..	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

SHIMOGA DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
2978	Ambargudda, H. S.	Ambargudda ..	Maratti ..	Sagar Taluka	Nagar, Kodur, Kodamavalli and Adagalatti
2979	Badankatte, H. S.	Tirumala Timmappanagudda.	Barnakatte ..	Sorab Taluka..	Tadasur, Amvatti and Kabbur
2980	Bisale, H. S.	Hulugudda Hill	Hossur ..	Tirthahalli Taluka.	Hosur, Sukkagudi, Megavalli and Hossur
2981	Chandragutti, H. S.	Chandragutti.	Chandragutti	Sorab Taluka	Bargavalli, Igoor and Kodumbi
2982	Dindemane, H. S.	Dindimanigudda	Karur ...	Sagar Taluka	Karur and Kaik
2983	Honnavalli, H. S.	Hanavalligudda	Hanavalli ...	Sorab Taluka	Honnavalli, Kodiyal and Hullatte
2984	Hugadi, H. S.	Hugaligudda ..	Hugadi ...	Nagar Taluka	Nagar and ..
2985	Kalasavangar, H. S.	Kalabigirigudda	Issaraptura ..	Honnali Taluka	Yeraguppa, Chikkenkatta and Hoblanatta
2986	Kalingarayan, H. S.	Kalingarayan ..	Halasinavaravu	Channagiri Taluka	Uru ..
2987	Kodachadri, H. S.	Kodachadri-parvata	Vallurmane ...	Sagar Taluka	Vallur, Vajkan, Sagar, Kattinamane and Kodur
2988	Kormargudda, H. S.	Kormargudda	Nyagar Khandaka.	Sagar Taluka	Thirumalai
2989	Siddeswara, H. S.	Siddesvaragudda.	Surali Balebail.	Tirthahalli Taluka.	Sugur, Balebail, Thirthamane, Sirigunda and Kerekatti
2990	Timmappanagudda, H. S.	Timmappanagudda.	Balavanakana-halli.	Channagiri Taluka	Bannikuppe ...
2991	Vamadi, H. S.	Vamadi ..	Kudagalmani	Shimoga Taluka	Sugur and Hire-

SHIMOGA DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and Rank of Inspecting Officer and dato of Inspection
Good				Mr. Krishnamachar, Amildar, 19-1-1931.
Platform of rough stones in mud with revetment on the exterior. No pillar or tower. A small excavation in the centre of the platform marks the site of the pillar. The Patel was instructed to keep the station clean.			12	K. Srinivasan Esq., Asst. Commissioner Rangappa, Amildar 10-12-30 10-12-30
Stones that ~~was~~ Label slipped from the platform were got replaced and the jungle round about the platform cleared at a tost of Rs. 3 only.	3/-	-		* M. Narayana Rao, Esq, Amildar. 28-12-30
A few stones from the basement on the eastern and northern sides have fallen down. But the platform does not require any immediate repairs.				K. G. Mahadevappa, Esq, Special Duty Amildar. 31-12-30.
It is in the same condition as last year. Requires repairs to the revetment of the platform. Last year's estimate not sanctioned	15	-		H. Krishnachar Dy Amildar 18-1-31.
Mound of katcha stones and earth with holes. No pillar or other structure visible.				K. Srinivasan Esq., Asst. Commissioner 8-12-30.
The platform and the space around it clear of rank growth, the upper portion of the pedastal is broken at the ~~edges and it requires~~ cement plastering.	4/-	-		K. Rangappa ..s Amildar. 8-12-30.
The station is quite firm; the debris is slightly in disrepairs owing to last mansoon rains. The pole was unstable and shaky. The debris must be set right and plastered. There is no rank vegetation around. A red flag was got placed on the pole	4/-			Mr. C. N. Gopalaswamy Naidu, Amildar 27-12-1930 B. Rachappa, Esq., Amildar 25-12-30
It is reported that the rank vegetation was got cleared up and trees grown near the platform were cut. The stones that were loose and that had fallen down were set right and fastened.	4/-			K Subba Rao, Amildar. 28-12-30.
Good				H. Krishnachar Dy Amildar 20-1-1931.
Quite good.				— do — 22-12-30.
One mark stone was taken off the pillars and thrown down the platform. The stone has been placed on the pillar (without mortar) and stones piled over it in the form of a cone to prevent its removal. jungle that has grown around was all cleared at a cost of Rs2/-	2/-			L. Narayana Rao Rao, Esq., Amildar 28-12-30.
The station was over-grown with rank grass which was got cleared. The stones of the pillar have been loosened and require to be fixed up with mortar otherwise the station is in good condition.	¼	-		N. S. Hiriannaiah Esq., Asst. Commissioner 30-12-1930. & T. Raja Rao, Esq. Amildar 27-12-30.

MYSORE DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

DESCRIPTION OF STATION.	PROTECTIVE MEASURES.
1. Hollow Towers of *Pakka* masonry ..	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station	

MYSORE DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
2438	Adhibetta, H. S.	Adhibetta ...	Hatnabettahalli	Mandya Taluka	Hatnabetta
2439	Adhurbetta, H. S.	Adhurbetta ...	Hallur Bedarahalli	Yedatore Taluka	Kuppe near Yedatore
2440	Bettadapur	Bettadapurada-betta.	Bettadapur ...	Hunsur Taluka	Bettadapur
2441	Halibetta, H. S.	Halibetta ...	Kachenahalli and Halatti	Nagamangala Taluka.	Kenchanahalli and Halatti
2442	Kundur	Kundurbetta ...	Kundur	Malavalli Taluka	Kundur
2443	Mysore No. 3, T. S.	Chamundibetta	Chamundibetta and Kudanhalli.	Mysore Taluka	Chamundibetta.
2444	Narayanagiri, H. S.	Narayanagiri-betta.	Siddapatna ...	Krishnarajpet Taluka.	Kadahalli, Siddapatna, Hanakere

MYSORE DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name and Rank of Inspecting Officer and dated of Inspection.
The Station is in good condition.				Mr. B. Lakshmana Rao, Amildar, Mandya Taluk. 30-12-1930.
Station is good, but the dry rough stone platform has gone in one or two places. A little mortar plastering to the main pedestal is necessary. The Patel of ~~K~~ Chikkakoppal and Revenue Inspector have been asked to complete the repairs and submit a bill so that it may not go worse.	2/-	-		Mr. Mahamad Ismail sheriff, Revenue S.D.O., Mysore Subdivision 29-10-1930
Both the platform ad the tower are in good condition. The chunnam patti running through the border of the tower at the bottom requires slight repairs. ~~Government sanctioned repairs to the extent of Rs. 2/- which will be got executed.~~				Mr. J. Appaji Gowda, Asst. Commissioner I/C French Rocks Sub Division 16-11-1930
				Mr. B. Sreenivasa Murthi, Amildar, Nagamangala on 16-11-1930
The platform and the pillar are in ~~good~~ good condition.				Mr. J. Appaji Gowda, Asst. Comissioner in charge of French Rocks Sub Division. 4-12-1930. Mr. H. N. Pallega Amildar, Krishnarajpet on 4-12-1930.

KOLAR DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

Description of Station.	Protective Measures.
1. Hollow Towers of *Pakka* masonry . .	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen down, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations:—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. ,, Platform Station ,,	s. ,, station ,,
S. ,, Station ,,	t. s. ,, tower station ,,
T. S. ,, Tower Station ,,	

KOLAR DISTRICT.

Ledger number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
1939	Ambajidurga, H. S	Ambajidurga..	Upparpet ..	Sidlaghatta now Chintamani Taluka.	Wa[illegible] Kavalgidurga, Chorangala and Kon[illegible].
1940	Bandapalle, H S.	Bandapallibetta	Bandapalli ..	Mulbagal Taluka.	Reddipalli Ellahalli Honnasettinalli Vurukunte and Mittur.
1941	Bhupatamma, H S	Bhupattamma-betta.	Uerhalli ..	Malur Taluka ..	Virakapuram, Somasamudra and Thimmanaikanhalli.
1942	Chikkapalli, H. S.	Chikkapalli ...	Chikkapalli ..	Sidlaghatta now Chintamani Taluka.	Yerra[illegible] halli, M[illegible] meri and Sadali.
1943	Itikaldurga, H. S.	Devekunte ...	Devekunte ..	Bagapalli Taluka.	Marganikunte and Thangedikunte in British Territory.
1944	Kolar, H S ..	Paparaganahalli-durga, belonging to the Kolar Village.	Paparaganapalli	Kolar Taluka ..	There are no villages in the vicinity.
1945	Konkontlu, H. S.	Siddramallibetta	Bodimpalli ..	Sidlaghatta now Chintamani Taluka.	Mungarihalli Bettalahalli Kodigallu and Dasarampalli.
1946	Kurudamale, H. S.	Kurudamalle-betta	Kurudamalle..	Mulbagal Taluka	Madagatta Siddagatta Rachabarahalli and Vaddahalli.
1947	Nandydroog, H. S.	Nandydroog ..	Sultanpet ..	Chikballapur Taluka.	Nandi, Kadavara and Virupahalli.
1948	Ramanajdar, H. S.	Ramanajdurga ..	Hosapet near Kalvara.	Sidlaghatta now Chintamani Taluka.	Kalvara.
1949	Yerrakonda, H. S.	Byatarayanaballi Betta.	Byatarayana Balli	Betmangala now Bowringpet Taluka.	Madanapalle, Doddakalle halli, Kempapura, Chamasamudram and Lakkinayakanahalli.

KOLAR DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	Name and Rank of Inspecting Officer and p. date of Inspection.
In good condition. Requires no repairs.			T.V.A.Isvaran Esq., B.A., Asst. Commissioner Chickballapur Sub Dn. on 18-9-30
In good condition except for the stone revetment requiring slight repairs.			S.N.Appanna Iyengar, Esq., B.A., BL, Asst. Commissioner Kolar Sub Dn. on 25-12-30.
In good condition except for the platform which requires little plastering.	10 Estimate has been called for.	-	Inspected by the Amildar of Malur Tk. on 31-12-30.
In good ~~condition~~ order.			T.V.A.Isvaran Esq., Asst. Commissioner Chickballapur Sub Dn.on 16-12-30.
In good condition.			-do- 7-12-30.
In good condition			The Amildar of Kolar Tk. on 30-12-30.
In good order.			T.VA. Isvaran Esq., BA, Asst Commissioner Chickballapur Sub Dn.18-9-30
In good condition, except at the corners of the mound on the sides which need replastering and cementing.	1	-	S.N.Appanna Iyengar, Esq., Asst.Commissioner Kolar Sub Dn.on 28-12-30.
Good --do--			T.V.A.Isvaran Esq., BA, Asst Commissioner, Chickballapur Sub Dn.on 22-12-30.
Jungle growth cleared and now in good condition.			--do-- 21-12-30.
In good condition except for the platform requiring plastering.	Estimate has been called for. 5	-	S.N.Appanna Iyengar, Esq., Asst. Commissioner Kolar Sub Dn.on 31-12-30.

BANGALORE DISTRICT.

ANNUAL RETURN SHOWING THE CONDITION OF THE PILLARS AND TOWERS OR PLATFORMS MARKING THE PRINCIPAL AND SECONDARY STATIONS OF THE TRIGONOMETRICAL SURVEYS.

Measures necessary for the protection of Stations.

Description of Station.	Protective Measures.
1. Hollow Towers of *Pakka* masonry ..	1. Stop all cracks; close the trap-door; block up the windows and the doors in the basement; and should the roof fall in, shape the *debris* in the form of a cone over the basement. If a pillar exists, cover it over with earth, or earth and stones in the form of a pyramid.
2. Solid Towers of *Kacha* masonry, with a central solid *Pakka* pillar.	2. Prevent water from percolating to the pillar, by stopping all cracks with mud, and cover the summit of the pillar with earth, sloped away to carry off the rainfall.
3. Solid Towers of *Kacha* masonry, with a central perforated *Pakka* pillar.	3. Adopt the same precautions as in 2, and close the passages leading to the ground level mark-stone with earth and stones if open.
4. Low platforms of *Kacha* materials with a central solid *Pakka* pillar.	4. Repair the platform and construct a pyramidal pile of earth, or earth and stones, over the pillar and partly resting on the platform.
5. *Pakka* pillars, circular above and square below.	5. Close the passages leading to the mark-stones with earth and mud, and prevent water lodigng near the base of the pillar.
6. *Pakka* pyramidal pillars	6. Cover over with earth and stones as in 4.

NOTE.

Remove vegetation from the roof of the pillars and the platforms, and keep the space round them clear.

The most important measure is to prevent the mark-stones in the basement of the pillars from being disturbed; when, therefore, a pillar has entirely fallen drwn, it will suffice if the *debris* is heaped over it in the form of a cone and plastered over with mud, which can be effected at a trifling expense. If it should, however, happen that the mark-stone has been removed, every endeavour should be made to preserve the site by raising a mound of earth, or of earth and stones, a few feet high over the spot whence the mark-stone has been removed.

In consequence of changes in the boundaries of districts, etc., any station in the Return which has changed its district should be noticed and correct district entered against it in the Return.

After filling in the last two columns, the Return should be sent, as soon as possible after 1st January, to the Superintendent, Trigonometrical Surveys, Dehra Dun.

As the funds available for the protection of stations do not allow of a greater average expenditure than Rs. 4 or 5 per station annually, the repairs should be restricted to the protective measures detailed above.

The following abbreviations are generally employed after the survey names of stations :—

H. S. denotes Hill Station (Principal)	h. s. denotes hill station (secondary.)
P. S. „ Platform Station „	s. „ station „
S. „ Station „	t. s. „ tower station „
T. S. „ Tower Station „	

BANGALORE DISTRICT.

Index number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana Taluka, Thana	Names of nearest villages
307	[illegible] betta, H. S.	Banarte-mari betta	Kotkonhalli ...	Kankanhalli Taluka.	Kotkonhalli
308	Bangalore Base-line, N. E. End. S	Kannur ...	Kannur ...	Hoskote Taluka.	Gubbi.
309	Bangalore Base-line, N. End. s.	Banasavadi ...	Banasavadi ...	Bangalore Taluka.	Channasandra.
310	Bangalore Base-line, S. End. s.	Harlur ...	Harlkunte ...	Bangalore Taluka.	Harlur
311	Bangalore Base-line S. W. End. S.	Cyal-dirne ...	Cyal-Kaval ...	Bangalore Taluka.	On the north of the Bangalore Cantonment.
312	Bannergatta, H. S.	Bannergatta ...	Bannergatta ...	Anekal Taluka.	Sampigenalli & Barrappanhalli
313	Basavanagudda, H. S.	Kodugpalli ...	Kodugpalli ...	Bangalore Taluka.	Kodugpalli
314	Doddagunta, s.	Doddagunta ...	Doddagunta ...	Civil & Military Station of Bangalore.	Jibanaha....
315	Gadalhalli, H. S.	Gadalhalli ...	Gadalhalli ...	Bangalore Taluka.	Gadalhalli.
316	Gubbi, s. ...	Kalsanhalli ...	Kalsanhalli ...	Hoskote Taluka.	Gubbi.
317	Halasur betta, H. S.	Alasur Hill ...	Betta Alasur ...	Devanhalli Taluka.	Sola Kempanhalli, Hilamanahalli and Sappanahalli.
318	Hennur, s. ...	Hennur ...	Hennur	Bangalore Taluka.	Hennur.

BANGALORE DISTRICT.

Condition of station	Estimated cost of repairs Rs.	a.	p.	Name & rank of Inspecting Officer and date of Inspection.
The Trigonometrical stone is lying in the Taluk office at Kankanhalli. It is learnt that as the stone had been removed from its place it was brought and kept in the Taluk office for being repaired after consulting the Survey of India Department in regard to the exact point.				Mr. V. Dwaraka nath, BA, B.L. Sub Dn. Officer Closepet.
Reported to be in good condition.				Mr. Abdul Hakh, BA., Sub Dn. Officer. 20-7-1930
Is in good condition.				Mr. Abdul Khader B.A., Sub Dn. Officer, 20-7-30.
Is in good condition.				-do- 19-7-30.
--do--				-do- 9-11-30.
--do--				-do- 6-7-30
Is in good condition.				Mr. T. Abdul Khadar, B.A. Sub Dn. Officer, 6-7-30.
Is in good condition.				Mr. T. Abdul Khader, B.A. Sub Dn. Officer.
--do--				12-7-30 --do-- 9-10-30
Reported to be in good condition.				Mr. M. Abdul Hakh, B.A., Sub Dn. Officer.
Is in good condition.				Mr. T. Abdul Khader, B.A Sub Dn. Officer. 9-11-30.

BANGALORE DISTRICT.

Index number	Survey name of station	Local name of station	Village in which the station lies	Tahsil, Pargana, Taluka, Thana	Names of nearest villages
319	Kalkote, h. s....	Kulkota ...	Kulkota ...	Dodballapur Taluka.	Varavani and Manchenahalli
320	Koppabetta, H. S.	Koppabetta ...	Kotakuppa ...	Kankanhalli Taluka.	Arakoppa and Dodkuppa
321	Machalbetta, s.	Lingarajpura...	Between Lingarajpura and Dodkunte.	Bangalore Taluka.	Lingarajpura.
322	Makkidurga, H. S.	Makkibetta ...	Makli ...	Dodballapura Taluka.	Somenahalli, Makli, Gundangiri and Kumbalahalli.
323	Mandur, H. S.	Dodgutta ...	Mandur ...	Hoskote Taluka	Gundur and Baiyappanahalli.
324	Nandigudi, H. S.	Nandigudi ...	Nandigudi ...	Hoskote Taluka	Banahalli.
325	Sampgehalli, t. s.	Sampgehalli ...	Sampgehalli ...	Bangalore Taluka.	Sriramapura and Sampgehalli.
326	Savandurga, H. S.	Savandurga ...	Karisavandurga near Basavana Temple.	Magadi Taluka	Nillapura, Kalsapura, Devarayanadoddi and Narasimhapalya.
327	Tirthalli, H. S.	Tirthalli ...	Tirthalli ...	Hoskote Taluka	Jodi Tirthalli.
328	Turkangutta, H. S.	Turkangutta ...	Doddanskandi	Bangalore Taluka.	Sitaramapalya.

BANGALORE DISTRICT.

Condition of station	Estimated cost of repairs			Name and Rank of Inspecting Officer and date of inspection
	Rs.	a.	p.	
Reported to be in good condition.				Mr. M. Abdul Hakh, B.A. Sub Divisio Officer.
Is fairly fixed				Mr. V. Dwarak nath, B.A., P.L., Sub Dn. Officer Closepet. 9-12-30
Is in good condition but requires sundry repairs	3		-	Mr. T. Abdul Khader, B.A Sub Divisio Officer. 20-7-30.
Reported to be in good condition.				Mr. M. Abdul Hakh, B.A., Sub Divisio Officer.
In good condition.				Mr. Abdul Hakh, B.A., Sub Divisio 11.11.30.
Pedestal has been completely demolished and the stone slab was found at a distance. Special report was submitted to the Deputy Commissioner to get the estimate sanctioned.	The estimate has been sanctioned and necessary action is being undertaken according to G.O. 2485-92/ P.P. 68-29-27 dated 13-12-1930.			Mr. M. Abdul Hakh, B.A., Sub Dn. Officer 26-9-30
Is in good condition.				Mr. T. Abdul Khader, B.A Sub Dn. Officer. 13-9-30.
It is reported ~~to be satisfactory.~~ that the base-stone fixed on the station is missing and that it has been removed and destroyed by some mischievous combers boy who frequent the place				Mr. V. Dwarak nath, B.A., B.L. Sub Dn. Officer, Closepot. 16-1-31
In good condition.				Mr. M. Abdul Hakh, B.A., Sub Dn. Officer. 11-11-30.
Is in good condition.				Mr. T. Abdul Khador - B.A., Sub Dn. Officer 18-9-30.

W D 1688—GPB—10-3-19—100

pillars and towers or platforms making the vertical survey in the Chitaldrug district for 1930.

(166

Names of nearest Villages	Condition of Station	Estimated cost of repairs
Hippirakere	Not inspected	
Panaikanahally	It is reported to be in the same condition as in the previous year. The Builder reports that the masonry platform all round requires repairs.	
Idavahosur Kattikosahally Thalya	The platform is reported to be in good condition; a few stones in the cone are reported to be somewhat loose. Rank vegetation is stated to have been got removed.	
Jagadahalli	Reported to be in good condition.	
Halebattu Neelanahalli Doggalli	The station is said to consist of one stone in the centre of which a circle is carved securely fixed on a platform built of rough stones piled up. The station is reported to be in good order.	
Hanapura Kamnahalli Kappanahalli Darkere in the Kallere Taluk	Reported to be in good condition.	
Gelialli Verlakere	Both the platform and the low circular towers are reported to be in good condition.	

A. 171/30-31

for Deputy Commissioner
Chitaldrug district.

Annual Return showing the condition of th
principal Stations of the Trigo

Ledger No.	Survey name of Station	Local name of Station	Village in which Station lies	Tahsil, pargana Taluk, Thana	
	Guheswaranagudda	Guheswaranagudda	Chikkondanahally	Chitaldrug Tq.	Ch
	Jogimatti	Jogimatti	State forest	— do —	Up
727	Hottegudda	Hottegudda	Kummingatta	Holalkere Tq.	Na
730	Shigekal Station	Shigekal gudda	Bharmannaikan-durga	— do —	
75	Bathigudda M.S.	Bathigudda	Doddabatti	Davangere Tq.	1. 2 3.
1	Jammapura	Jammapura chowdi gudda	Jammapura	Hosadurga Tq.	Ja ch M B H
2	Utare Gudda in The Marikanive State forest	Utare gudda	Higelalli	— do —	Hl

Chitaldrug
07. 27/1/31

A3. per

the principal stations of the Trigonometrical

t for 1930.

, Names of nearest villages.	Condition of station.	Name and rank of the officers who inspected the stations and the date of inspection.
Chippinakere	Not inspected.	
Uppanaikanahally.	It is reported to be in the same condition as in the previous year. The Amildar reports that the masonry platform all round requires repairs	Amildar, Chitaldrug, Mr H. Venkatasubba Rao 19-1-30.
Nandanahosur, Ghattihosahally, Thalya.	The platform is reported to be in good condition; a few stones in the one are reported to be some what loose. Rank vegitation is stated to have been got removed	Amildar, Holalkere, Mr. K. Gundu Rao. 27-11-30.
Tyagadahalli	Reported to be in good condition.	Sub-division officer, Davangere, Mr T. Ramiah. 22-7-30.
1. Halchatti 2. Neelanahalli 3. Doggalli	The station is said to ~~be~~ consist of one stone (in the centre of which a circle is carved) securely fixed on a platform built of rough stones piled up. The station is reported to be in good order.	Amildar, Davangere, Mr. K. Madhava Rao. 21-11-30.
Jammapura Chikkamnahalli Mallappanahalli Biderkere in the Holalkere Taluk	Reported to be in good condition.	Sub-division officer, Davangere, Mr. T. Ramiah along with the Amildar, Mr. A. Arunachalam 9-9-30.
Ittigehalli Nerlakere	Both the platform and the low circular tower are reported to be in good condition.	Amildar, ~~Kudligi~~ Hosadurga Mr. A. Arunachalam 31-12-30.